



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En AutomobileINDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Ref: CS/III22009298/Uny3

Date: 21/09/2022

Code: III2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDQ 971K
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From GABRIEL WEE	Assign Date	21/09/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 19/09/2022	Inspection Date 21/09/2022
Survey held at HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--