

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009300/UPA3Q2**Date:** 05/10/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002583680
Claimant Vehicle No :	SLA266C	Insured Vehicle No :	SLS2339T
Date of Loss:	16/09/2022	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA266C		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGFU068960
Reg. Date:	19/02/2016 (Man. Year: 2015)	Chassis No:	KMHDH41CMGU656583
Colour:	Silver	Odometer:	303278 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,956.80	3,912.80	8,044.00	67.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	2,400.00	2,040.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,396.80	6,312.80	10,084.00	61.50
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	16,396.80	5,000.00	11,396.80	69.51
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	20/09/2022	
Date Inspected:	21/09/2022 Inspected At:	2ND Auto Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre Singapore 417808
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA266C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	1,081.00 FL	*- FL
2	2		*REAR BUMPER BRACKET	Not Necessary	60.00 FL	*- FL
3	2		*REAR BUMPER RETAINER	Not Necessary	68.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	348.00 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	88.00 FL	*- FL
6	1		*FRONT LEFT DOOR ASSY	Badly Dented	1,297.00 FL	*1,297.00 FL
7	1		*FRONT LEFT DOOR INNER LOCK	Not Necessary	257.00 FL	*- FL
8	1		*FRONT LEFT DOOR TRIM BOARD	Deformed / Torn	479.00 FL	*479.00 FL
9	1		*FRONT LEFT DOOR OUTER HANDLE	Not Necessary	179.00 FL	*- FL
10	1		*FRONT LEFT DOOR BLACK STICKER	Necessary	28.00 FL	*28.00 FL
11	1		*FRONT LEFT DOOR POWER WINDOW REGULATOR WITH MOTOR	Bent / Jammed	496.00 FL	*496.00 FL
12	1		*FRONT LEFT SILL PANEL	Dented	1,287.00 FL	*1,287.00 FL
13	1		*FRONT LEFT DOOR CHECKER LINKAGE	Not Necessary	165.00 FL	*- FL
14	2		*FRONT LEFT DOOR HINGES	Not Necessary	162.00 FL	*- FL
15	1		*FRONT LEFT DOOR OUTER MOULDING	Not Necessary	198.00 FL	*- FL
16	1		*FRONT LEFT B PILLAR	Repair	985.00 FL	*- FL
17	1		*REAR LEFT DOOR ASSY	Badly Dented	1,276.00 FL	*1,276.00 FL
18	1		*REAR LEFT DOOR OUTER MOULDING	Not Necessary	198.00 FL	*- FL
19	1		*REAR LEFT DOOR INNER LOCK	Not Necessary	257.00 FL	*- FL
20	1		*REAR LEFT DOOR TRIM BOARD	Not Necessary	479.00 FL	*- FL
21	1		*REAR LEFT DOOR OUTER HANDLE	Not Necessary	179.00 FL	*- FL
22	1		*REAR LEFT DOOR BLACK STICKER	Necessary	28.00 FL	*28.00 FL
23	2		*REAR LEFT DOOR HINGES	Not Necessary	162.00 FL	*- FL
24	1		*REAR LEFT DOOR CHECKER LINKAGE	Not Necessary	165.00 FL	*- FL
25	1		*REAR LEFT DOOR POWER WINDOW REGULATOR WITH MOTOR	Not Necessary	496.00 FL	*- FL
26	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	186.00 FL	*- FL
27	1		*REAR LEFT FENDER ASSY	Repair	1,417.00 FL	*- FL
28	1		*REAR LEFT FENDER INNER COWLING	Not Necessary	192.00 FL	*- FL
29	1		*REAR LEFT TAILLAMP	Not Necessary	883.00 FL	*- FL
30	12		*REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
31	1		*REAR LEFT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
32	6		*REAR LEFT FENDER INNER COWLING CLIPS	Not Necessary	40.00 FS	*- FS
33	8		*FRONT LEFT DOOR TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
34	8		*REAR LEFT DOOR TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
35	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
36	1		*REAR LEFT TYRE	Serviceable	350.00 FS	*- FS
37	1		*REAR LEFT WHEEL RIM	Repair	750.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,576.00	4,891.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,619.20	978.20
Total Parts (\$\$)	11,956.80	3,912.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN ACCIDENT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS	New	1,600.00	1,000.00
2	TO PUTTY AND SPRAY PAINTING FRONT LEFT AND REAR LEFT PORTION	New	1,600.00	1,080.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	60.00
5	TO APPLY ANTI RUST PROOFING TO FRONT LEFT AND REAR LEFT AFFECTED AREA	New	140.00	60.00
6	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	0.00
7	TO BALANCE REAR LEFT WHEEL	New	50.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
9	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM	New	80.00	60.00
10	TO REMOVE AND INSTALL REAR LEFT DOOR LOCK MECHANISM	New	80.00	60.00
11	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION	New	80.00	0.00
12	TO TRANSFER REAR LEFT DOOR GLASS TO NEW DOOR	New	80.00	0.00
13	TO TRANSFER FRONT LEFT DOOR GLASS TO NEW DOOR	New	80.00	0.00
14	TO REMOVE AND INSTALL FRONT LEFT DOOR REGULATOR WITH MOTOR ASSY	New	80.00	0.00
15	TO REMOVE AND INSTALL REAR LEFT DOOR REGULATOR WITH MOTOR ASSY	New	80.00	0.00
16	TOWING SERVICES	New	100.00	0.00
Gross Labour Cost (\$\$)			4,440.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >