

HSIAO Tony Reject case

Not Authorized

21/09/22

4/5 @ 5000
5 days

SLA266C Hyundai Elantra

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>2</i>	\$ 1,081.00 X
2	2	Rear bumper bracket <i>11</i>	\$ 60.00 X
3	2	Rear bumper retainer <i>11</i>	\$ 68.00 X
4	1	Rear bumper reinforcement <i>2</i>	\$ 348.00 X
5	1	Rear bumper tow cover <i>11</i>	\$ 88.00 X
6	1	Front left door aasy <i>body 2</i>	\$ 1,297.00 /
7	1	Front left door inner lock <i>11</i>	\$ 257.00 X
8	1	Front left door trim board <i>del/b. 1</i>	\$ 479.00 /
9	1	Front left door outer handle <i>11</i>	\$ 179.00 X
10	1	Front left door black sticker <i>2</i>	\$ 28.00 /
11	1	Front left door power window regulator with motor <i>2</i>	\$ 496.00 /
12	1	Front left sill panel <i>2</i>	\$ 1,287.00 /
13	1	Front left door checker linkage <i>11</i>	\$ 165.00 X
14	2	Front left door hinges <i>11</i>	\$ 162.00 X
15	1	Front left door outer moulding <i>11</i>	\$ 198.00 X
16	1	Front left B pillar <i>2</i>	\$ 985.00 X
17	1	Rear left door assy <i>body 2</i>	\$ 1,276.00 /
18	1	Rear left door outer moulding <i>11</i>	\$ 198.00 X
19	1	Rear left door inner lock <i>11</i>	\$ 257.00 X
20	1	Rear left door trim board <i>11</i>	\$ 479.00 X
21	1	Rear left door outer handle <i>11</i>	\$ 179.00 X
22	1	Rear left door black sticker <i>2</i>	\$ 28.00 /
23	2	Rear left door hinges <i>11</i>	\$ 162.00 X
24	1	Rear left door checker linkage <i>11</i>	\$ 165.00 X
25	1	Rear left door power window regulator with motor <i>11</i>	\$ 496.00 X
26	1	Rear windscreen glass moulding <i>11</i>	\$ 186.00 X
27	1	Rear left fender assy <i>2</i>	\$ 1,417.00 X
28	1	Rear left fender inner cowlings <i>11</i>	\$ 192.00 X
29	1	Rear left taillamp <i>11</i>	\$ 883.00 X
			\$ 13,096.00
Less 20%			\$ 2,619.20
			\$ 10,476.80
<u>Special Nett Items</u>			
1	12	Rear bumper clips <i>11</i>	\$ 60.00 X
2	1	Rear left fender sealant <i>11</i>	\$ 100.00 X
3	6	Rear left fender inner cowlings clips <i>11</i>	\$ 40.00 X
4	8	Front left door trim board clips <i>11</i>	\$ 40.00 X
5	8	Rear left door trim board clips <i>11</i>	\$ 40.00 X
6	1	Rear windscreen glass sealant <i>11</i>	\$ 100.00 X
7	1	Rear left tyre <i>2</i>	\$ 350.00 X
8	1	Rear left wheel rim <i>2</i>	\$ 750.00 X
			\$ 1,480.00
Total parts			\$ 11,956.80

SLA266C Hyundai Elantra

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,600.00	1090
2	To putty and spray painting front left and rear left portion.	\$ 1,600.00	1080
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00	60
5	To apply anti rust proofing to front left and rear left affected area.	\$ 140.00	60
6	To remove and install rear bumper reverse sensor.	\$ 80.00	X
7	To balance rear left wheel.	\$ 50.00	X
8	To conduct wheel alignment.	\$ 120.00	60
9	To remove and install front left door lock mechanism.	\$ 80.00	60
10	To remove and install rear left door lock mechanism.	\$ 80.00	60
11	To check door central locking for function.	\$ 80.00	X
12	To transfer rear left door glass to new door.	\$ 80.00	X
13	To transfer front left door glass to new door.	\$ 80.00	X
14	To remove and install front left door regulator with motor assy.	\$ 80.00	X
15	To remove and install rear left door regulator with motor assy.	\$ 80.00	X
16	Towing services	\$ 100.00	X
Total labour :		\$ 4,440.00	

Total parts : \$ 11,956.80

Total labour : \$ 4,440.00

Total repair cost : \$ 16,396.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-4891
202
3912.8
2400
6312.80
202
5050