

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 4271Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR -RH (N) (CONSISTENT)	BENT	2,240.00	2,240.00
1	FRONT DOOR HINGES -RH @\$170.00 (N) (CONSISTENT)	TO REPAIR SEE LABOUR	340.00	-
1	FRONT RH DOOR FRAME WEATHERSTRIP (N) (CONSISTENT)	NECESSARY	300.00	300.00
1	FRONT DOOR SEAL (FRONT)RH (N) (CONSISTENT)	SERVICEABLE	45.00	-
1	FRONT RH FENDER (N) (CONSISTENT)	BENT	1,020.00	1,020.00
1	FRONT RH SPORT RIM (N) (CONSISTENT)	SERVICEABLE	865.00	-
	LESS 10% DISCOUNT		-481.00	-356.00
			4,329.00	3,204.00
	SPECIAL NETT ITEMS			
20	FRONT DOOR TRIMBOARD RIVETS RH @\$12.00 (SN) (CONSISTENT)	NECESSARY	240.00	60.00
			240.00	60.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT FRONT RH DOOR MECHANISM TO FACILITATE REPAIR.		150.00	60.00
	TO REMOVE AND REFIT FRONT RH FENDER TO NEW PARTS.	NOT NECESSARY	120.00	-
	TO PUTTY AND SPRAY ON THE AFFECTED AREAS .		800.00	440.00
	TO CHECK WHEEL ALIGNMENT BY COMPUTERISED.	NOT NECESSARY	250.00	-
	TO PANEL BEAT & STRAIGHTEN RH FRONT FENDER INNER PANEL ,RH FRONT DOOR PILLAR ,RH FRONT CHASSIS FRAME ,INCLUDING REPLACEMENT OF PARTS REFIT AND ADJUSTE THE SAME.INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGES -RH.		800.00	400.00
			2,120.00	900.00
	GRAND TOTAL		6,689.00	4,164.00

Report Ref No. CC4/ASM22009301/Kpa3q2

KONG SENG CHEONG

**Licensed Appraiser**