

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	810H
Vehicle Details	
Vehicle No.:	SLL2150G
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Sep 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP6EAT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	PE20838220
Chassis No.:	JM6GL1071H0104749
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$24,910.00
Original Registration Date:	17 Feb 2017
First Registration Date:	17 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$26,874.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Feb 2027
PARF Rebate Amount:	\$18,811.00
Intended COE Rebate Details	
COE Expiry Date:	16 Feb 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,209.00
COE Rebate Amount:	\$21,262.00
Total Rebate Amount:	\$40,073.00

The information contained herein is correct as at 20 Sep 2022

OK

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST: 201006949C RCB NO: 201006949C

Not Authorized
del
array
3/10/22
2/58
Ydy
John, the

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 Anson Road
Springleaf Tower #16-00
Singapore 079909
TEL: 63896111 FAX: 6221033
ATTN: Motor Claim Department \ CHINA

Estimate No: EST1508675
Date: 20 Sep 2022
Policy No: DMPC22B00006901
Veh Reg No: SLL2150G
Make/Model: MAZDA MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Chassis No: JM6GL1071H0104749
Engine No: PE20838220
Reg. Date: 17/02/2017

Your Ref No: TP 0922-7002
Claim Type: Third Party
Accident Date: 20/09/2022
TP Veh Reg No: SMK 8550 P

Estimate Repair Cost to Vehicle No :SLL2150G

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER WITH LOWER (BLACK) <i>For</i>	1,099.000	1 PC	1,099.00	—
2 REAR BUMPER SIDE HOLDER - LH/RH <i>del</i>	42.0000	2 PC	84.00	—
3 REAR BUMPER CLIPS <i>del</i>	5.9000	10 PC	59.00	—
4 REAR BUMPER REINFORCEMENT <i>del</i>	538.0000	1 PC	538.00	—
<i>1 set</i> 5 REAR BUMPER SENSOR <i>shut</i>	195.0000	4 PC	780.00	250 S/W
6 REAR BUMPER SENSOR COVER <i>11</i>	29.0000	4 PC	116.00	X
7 REAR BUMPER SENSOR WIRE <i>11</i>	127.0000	1 PC	127.00	X
8 REAR BUMPER TOWING COVER - LH/RH <i>del/m</i>	48.0000	2 PC	96.00	—
9 REAR BUMPER REFLECTORS - LH/RH <i>11</i>	49.0000	2 PC	98.00	X
10 REAR BUMPER BRACKETS - LH/RH <i>11</i>	43.0000	2 PC	86.00	—
11 REAR PANEL <i>11</i>	606.0000	1 PC	606.00	X
12 REAR PANEL TOP GARNISH <i>11</i>	149.0000	1 PC	149.00	X
13 REAR BOOT LOCK SENSOR <i>11</i>	213.0000	1 PC	213.00	X
14 REAR BOOT <i>del/11</i>	1,115.000	1 PC	1,115.00	—
15 REAR BOOT OUTER GARNISH - CHROME <i>11</i>	302.0000	1 PC	302.00	X
16 REAR BOOT GLASS MOULDING <i>11</i>	106.0000	1 SET	106.00	X
17 REAR BOOT TOP LOCK <i>del/11</i>	160.0000	1 PC	160.00	—
18 REAR BOOT BOTTOM LOCK <i>11</i>	79.0000	1 PC	79.00	X
19 REAR BOOT RUBBER <i>11</i>	114.0000	1 PC	114.00	—
20 REAR BOOT MAZDA LOGO <i>del</i>	57.0000	1 PC	57.00	—
21 REAR BOOT MAZDA 6 LOGO <i>del</i>	28.0000	1 PC	28.00	—
22 REAR BOOT SKYACTIVE LOGO <i>del</i>	66.0000	1 PC	66.00	—
23 REAR EXHAUST PIPE WITH CHROME <i>11</i>	1,486.000	1 PC	1,486.00	X
			7,564.00	
		Less 20%	1,512.80	6,051.20
Special Net				
24 REAR NUMBER PLATE WITH CASING <i>500</i>	35.0000	1 SET	35.00	—
25 REAR BOOT CAMERA <i>del</i>	350.0000	1 SET	350.00	X
26 SEALANT <i>11</i>	20.0000	2 PC	40.00	X
27 SPONGE TAPE <i>11</i>	20.0000	1 PC	20.00	X
			445.00	445.00
Labour				
28 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	580
29 TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.0000	1 JOB	900.00	680

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Estimate No: EST1508675

Date: 20 Sep 2022

Policy No: DMPC22B00006901

Veh Reg No: SLL2150G

Make/Model: MAZDA MAZDA6 4-
DOOR SEDAN 2.0L
SP.6EAT

Chassis No: JM6GL1071H0104749

Engine No: PE20838220

Reg. Date: 17/02/2017

Your Ref No: TP 0922-7002

Claim Type: Third Party

Accident Date: 20/09/2022

TP Veh Reg No: SMK 8550 P

Estimate Repair Cost to Vehicle No :SLL2150G

Description	U/Price	Quantity	Price	Amount
30 TO CHECK WIRING	50.0000	1 JOB	SS 50.00	SS
31 TO TUFF-KOTE	60.0000	1 JOB	60.00	20
32 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	30
33 TO REMOVE, REFIT REAR GARNISH, CUSHION, CARPET AND RELATED PARTS	150.0000	1 JOB	150.00	50
34 TO REMOVE, REPLACE REAR EXHAUST PIPE	80.0000	1 JOB	80.00	80
			17 80.00 X	
			2,140.00	2,140.00
Total				SS 8,636.20
Add GST @ 7%				604.53
Total Amount Payable				SS 9,240.73

TOTAL: SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED FORTY AND CENTS SEVENTY THREE ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: