

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	F	Ref:	CS3/LPC22009310/Eny3m4
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Γ	Date:	07/11/2022
			C	Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMC 7474A	Veh. Inspected		SMH 4861J
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/22/22/V05/026255	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		21/09/2022
2.	Vehicle Particulars & Condition				
	Make & Model	BMW 318I	c.c		1995
	Engine No.	HIDDEN	Year of Reg.		2010
	Chassis No.	WBAPF720X0A794046	Colour		WHITE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/45 R17	CONTINENTAL		4 mm
	L/H Front Tyre	215/45 R17	CONTINENTAL		4 mm
	R/H Rear Tyre	215/45 R17	CONTINENTAL		4 mm
	L/H Rear Tyre	215/45 R17	CONTINENTAL		4 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT O/S PORTION.			
5.	General Information				
	Accident Date	03/09/2022	Inspect Date / Ti	ime	21/09/2022 (03:21 PM)
	Survey held at	40 Toh Guan Road East #01-67 Enterprise Hub			
	Repairer	MASTER CAR SPRAY SERVICE			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22009310/Eny3m4

Inspected By

CHEN TSUE YEE

CHEN TSUE YEE
Automotive Assessor

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser