

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAI	NCE BHD		Ref:	CS3/LPC22009310/En2y3
	300 BEACH ROAD			Date:	21/09/2022
	#17-04/07 THE CC	NCOURSESINGAPORE 199555		Code:	LDC2
4		Delieu Dewtieuleus	/TUIDD DARTY		
1.	Insured Veh.	Policy Particulars :- SMC 7474A	1		SMH 4861J
		SIVIC 1414A	Veh. Inspected		0.00
	Policy No.	20/00/00/00/00/00/00	Coverage (\$)		
	Claim No.	22/22/22/V05/026255	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		21/09/2022
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5. General Information					
	Accident Date	03/09/2022	Inspection Date	9	21/09/2022
	Survey held at 40 Toh Guan Road East #01-67 Enterprise Hub Repairer MASTER CAR SPRAY SERVICE				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
		EASE FIND DAMAGED VEHICLE	PHOTOGRAPHS.		