



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: GBE3696Y

Report No: AAS/2022/204

Appraisement Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	LHR wheel guard (Frt)	1	Dented	\$ 220.30	\$ 220.30 201.40
			281.40 18% 188.146	Total: \$ 220.30 -10% \$ 22.03 Nett total: \$ 198.27	\$ 220.30 \$ 22.03 \$ 198.27
1	LH sliding door (Frt)	1	Dented	\$ 1,400.00	\$ 1,400.00 1000
2	LH sliding door (Rr)	1	Dented/Repair	\$ 1,400.00	-
3	LH sliding door rail	1	Dented/Repair	\$ 650.00	-
4	Rear box sticker (Customised)	1set	Necessary	\$ 2,800.00	\$ 2,800.00 2000
			3000	Special nett total: \$ 6,250.00	\$ 4,200.00

Parts Total: \$ 6,448.27 \$ 4,398.27

S/N	Labour Description	Repairer's Est	Revised Est
1	To check lightings & wirings. kan	\$ 50.00	\$ 30.00 X
2	To remove and renew rear box vinyl wrap	\$ 250.00	\$ 250.00 100
3	To remove and renew damaged parts. Re-align all affected area.	\$ 600.00	\$ 440.00 300
4	To putty and respray all damaged parts. Touch up all affected area.	\$ 500.00	\$ 300.00 200
	Labour Total:	\$ 1,400.00	\$ 1,020.00

Grand Total: \$ 7,848.27 \$ 5,418.27

The final adjusted lump sum amount is \$4,350.00

Under normal circumstances, the repair should be completed within a reasonable period of 5 working days.

24 Photographs were taken at the time of inspection.

188.146
2000.00
600.00
3788.146
200
3030.76

2/3 - \$3,000/4 days

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.