

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



DATE : 16.09.2022

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKT9207B**
MODEL : **TOYOTA COROLLA ALTIS**
DATE OF ACCIDENT : ~~16-09-2022~~ 15/09/22
TIME OF ACCIDENT : 17:50 HRS

MRO53REH04534529
Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Debond</i>	1	\$ 515.10	\$ 515.10
2	REAR BUMPER REFLECTOR <i>1H cut</i>	2	\$ 75.10	\$ 150.20
3	REAR BUMPER SIDE RETAINER <i>2nd</i>	2	\$ 105.10	\$ 210.20
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 395.10	\$ 395.10
5	REAR BUMPER REINFORCEMENT BRACKET <i>AT</i>	2	\$ 90.10	\$ 180.20
6	BOOTLID <i>Dented</i>	1	\$ 756.10	\$ 756.10
7	BOOTLID CENTER MOULDING <i>cut</i>	1	\$ 237.10	\$ 237.10
8	BOOTLID DETECTOR <i>new</i>	1	\$ 385.00	\$ 385.00
9	BOOTLID LOGO <i>new</i>	1	\$ 85.00	\$ 85.00
10	BOOTLID LAMP <i>Lit ut</i>	2	\$ 342.00	\$ 684.00
11	BOOTLID EMBLEM 'COROLLA' <i>3 new</i>	1	\$ 70.00	\$ 70.00
12	BOOTLID EMBLEM 'ALTIS'	1	\$ 70.00	\$ 70.00
13	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
14	BOOTLID TOP LOCK <i>2nd</i>	1	\$ 318.10	\$ 318.10
15	BOOTLID LOWER LOCK <i>new</i>	1	\$ 20.00	\$ 20.00
16	BOOTLID WEATHERSTRIP <i>at</i>	1	\$ 195.00	\$ 195.00
17	TAILLAMP <i>Lit ut</i>	2	\$ 465.00	\$ 930.00
18	TAILLAMP PANEL <i>Regis</i>	2	\$ 198.00	\$ 396.00
19	TAILLAMP LOWER BARCKET <i>new</i>	2	\$ 115.10	\$ 230.20
20	REAR FENDER LH <i>Dented</i>	1	\$ 987.00	\$ 987.00
21	REAR FENDER INNER COWLING <i>new</i>	2	\$ 350.20	\$ 700.40
22	REAR FENDER INNER TRIM <i>new</i>	2	\$ 770.10	\$ 1,540.20
23	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 163.00	\$ 163.00
24	REAR WHEEL RIM RH <i>at</i>	1	\$ 985.00	\$ 985.00
25	REAR ABS SENSOR RH <i>new</i>	1	\$ 295.00	\$ 295.00
26	REAR WHEEL HUP C/W BEARING RH <i>new</i>	1	\$ 810.00	\$ 810.00

25.10
342
865 391
480(SN)

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKT9207B**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 16.09.2022
 TIME OF ACCIDENT : 17:50 HRS

27	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 390.00	\$ 390.00	x
28	REAR AXLE <i>new</i>	1	\$ 2,850.00	\$ 2,850.00	t.
29	REAR END PANEL <i>Dented</i>	1	\$ 695.30	\$ 695.30	—
30	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 250.10	\$ 250.10	✓
31	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 271.10	\$ 271.10	+
32	REVERSE SENSOR (SET) <i>new</i>	1	\$ 368.20	\$ 368.20	✓

SN: 480
 6123.40
 4592.55

TOTAL PRICE \$ 16,272.60
 LESS 25% \$ 4,068.15
SUB TOTAL PRICE \$ 12,204.45

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00	x
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	x.
4	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10.
5	TAILLAMP PANEL SEALANT LH <i>new</i>	1	\$ 60.00	\$ 60.00	+
6	REAR FENDER SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00	60
7	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	x
8	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
9	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
10	REAR WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	10
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR WHEEL TYRE LH <i>new</i>	1	\$ 480.00	\$ 480.00	x.
14	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+

240

TOTAL \$ 1,940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	1200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	TUFF COAT	\$ 250.00	100
4	WIRING CHECK	\$ 180.00	30

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKT9207B**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 16.09.2022
 TIME OF ACCIDENT : 17:50 HRS

5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80.
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	+
8	TRANFER BOOTLID MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+
10	REMOVE AND REFIX FUEL TANK TO FACILIATE FLOOR PANEL REPLACEMENT	\$ 80.00	+
11	FOUR WHEEL ALIGNMENT	\$ 120.00	80
12	RESET ABS LIGHT	\$ 350.00	+
13	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	+

TOTAL \$ 5,930.00

TOTAL PARTS COST : \$ 14,144.45
 TOTAL LABOUR COST : \$ 5,930.00
 TOTAL REPAIR COST : \$ 20,074.45

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L

1/s 16/09/22.

08 Days

Total: 7912.55

1/s: 6.31K