

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009315/KVY3Q2**Date:** 08/11/2022**REFERENCE**

Insured/Claimant:	ALI SUSANTO	Policy No:	202222006903SL	
Date of Loss:	18/09/2022	Nature of Claim:	OD	Claim No: 202222006903SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGC730C		
Make & Model:	BMW X3, 2.0 (A)	Engine No:	B1640619N20B20A
Reg. Date:	28/02/2014 (Man. Year: 2013)	Chassis No:	WBAWX320300B28561
Colour:	Metallic Red	Odometer:	134488 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$64,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50Z R18	Rear Tyre Size:	245/50Z R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,508.00	4,805.00	703.00	12.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	880.00	1,190.00	57.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,578.00	5,685.00	1,893.00	24.98
Approved Total (Overridden) (S\$)		4,500.00		
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	6,878.00	3,800.00	3,078.00	44.75
+ GST 7.00/7.00% (S\$)	481.46	266.00	215.46	44.75
Nett Amount (S\$)	7,359.46	4,066.00	3,293.46	44.75

INSPECTION

Date of Assignment: 21/09/2022

Date Inspected: 22/09/2022 Inspected At:

Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
Parts:	M1-SUV	BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC730C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH (WCP)	Cracked	1,800.00 F	*1,800.00 F
2	1		*FRONT HEADLAMP LOWER BRACKET RH (WCP)	Serviceable	95.00 F	*- F
3	1		*FRONT FENDER RH (WCP)	Bent	500.00 F	*500.00 F
4	1		*FRONT FENDER WHEEL ARCH GARNISH RH (WCP)	Dented / Distorted	180.00 F	*180.00 F
5	1		*FRONT FENDER INNER SHIELD RH -FRONT (WCP)	Distorted / Cracked	135.00 F	*135.00 F
6	1		*FRONT FENDER INNER SHIELD RH -REAR (WCP)	Serviceable	135.00 F	*- F
7	1		*FRONT BUMPER (WCP)	Bent	1,250.00 F	*1,250.00 F
8	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Distorted	85.00 F	*85.00 F
9	1		*FRONT BUMPER LOWER (WCP)	Cracked	300.00 F	*300.00 F
10	1		*FRONT DOOR RH (NPA) (WCP)	Repair	0.00 F	*- F
11	1		*FRONT SPORT RIM RH (NPA) (WCP)	Repair	0.00 F	*- F
12	1		*FRONT FENDER WHEEL ARCH GARNISH CLIPS RH	Necessary	40.00 FS	*40.00 FS
13	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	40.00 FS	*40.00 FS
14	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
15	1		*FRONT TYRE RH	Serviceable	450.00 FS	*- FS
					Sub Total (\$\$)	5,060.00 4,380.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	448.00 425.00
					Total Parts (\$\$)	5,508.00 4,805.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE REPLACE ,REFIX REPAIR & READJUST ACCIDENT AREAS	New	800.00	400.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	800.00	440.00
3	TO FRONT WHEEL ALIGNMENT AND BALANCING	New	100.00	20.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	20.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	0.00
Gross Labour Cost (\$\$)			2,070.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >