

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1988 GST Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	L INSURANCE (S) PL	F	Ref:	CS/AGI22009318/Gcy3m4	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	11/05/2023	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLN 3613X	Veh. Inspected		SMN 3664L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10017633/JL	Excess (\$)		0.00	
	Assign From	SALIZAWATI	Assign Date		21/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180	c.c		1332	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	WDD1183842N007996	Colour		GREY	
	Odometer	42585 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	225/40ZR19	FALKEN		6 mm	
	L/H Front Tyre	225/40ZR19	FALKEN		6 mm	
	R/H Rear Tyre	225/40ZR19	FALKEN		6 mm	
	L/H Rear Tyre	225/40ZR19	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	20/09/2022	Inspection Date		04/10/2022	
	Survey held at	JACK CARS ENTERPRISE PTE LTD				
		BLK 3007 UBI ROAD 1 #01-450 SINGPORE 408700				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: