

FIRST AUTOWORKS

Repair Estimate

Date : 05/09/2022

Reference: SGR 1008U
Make: Mercedes
E200

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SGR 1008U
CHASSIS NO.: WDD2130422A501964
ENGINE NO.: 27492031577191

TRAI G.
Xiao Tony

Name of insured : WU CHEOK KWAN JACKSON
Date of accident.: 27/08/2022

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RR BUMPER CENTRE <i>del d</i>	1650.00 ✓
2	1	RR BUMPER LOW GARNISH(SILVER) <i>new</i>	43.00 ✓
3	1	RR BUMPER REFLECTOR RH <i>2</i>	68.00 + <i>1650</i>
4	1	RR BUMPER REFLECTOR LH <i>1</i>	68.00 +
5	1	RR BUMPER TOW COVER <i>1</i>	78.00 ✓ <i>1485</i>
6	1	RR BUMPER SIDE RETAINER RH <i>3</i>	101.00 +
7	1	RR BUMPER SIDE RETAINER LH <i>3</i>	101.00 +
8	1	RR BUMPER CENTER RETAINER <i>new</i>	78.00 +
9	1	RR BUMPER REINFORCEMENT <i>new</i>	876.00 +
10	2	RR BUMPER REVERSE SENSOR - INNER <i>3</i>	500.00 +
11	2	RR BUMPER REVERSE SENSOR RUBBER SEAL <i>1</i>	70.00 +
12	1	RR BUMPER REVERSE SENSOR WIRE HARNESS <i>1</i>	665.00 ✓

Parts Total: \$4,298.00
Less 10%: \$429.80
Total : \$3,868.20

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	1200.00 <i>250</i>
2	Carry out spray painting on accident affected area. (Rear bumper, Rear end panel)	1340.00 <i>250</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 ✓ <i>550</i>
4	Remove and replace reverse sensor (Labour)	80.00 ✓ <i>50</i>

Labour Total : \$2,700.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Other

Labour Description

<u>No.</u>		<u>Price (SGD)</u>
1	Rear Number Plate & Farnie <i>He me</i>	40.00 <i>x</i>

Other Total: \$40.00

Total : \$6,608.20
 Gst (7%) : \$462.57
GRAND TOTAL: \$7,070.77

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, Y WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor
 Ronnie Tan
 DID: 6844 1985 Fax:6844 5185

Adrian Li
P/P 20/09/22

02 Days

total: 2035
(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

GST Ref. No: M2-0111811-E

Vehicle No: SGR 1008U
Chasis No : WDD2130422A501964
Engine No: 27492031577191

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

<u>No.</u>	<u>Qty.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	1	RR BUMPER CENTRE	1650.00

Total: 1650.00
Less 10%: 165.00
Parts Total : 1485.00

Labour

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair	250.00
2	Carry out spray painting on accident affected area. (Rear bumper)	250.00
3	Remove and replace reverse sensor (Labour)	50.00

Labour Total : 550.00

Sub Total : 2035.00
GST (7%) 142.45
Grand Total: 2177.45

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.