

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 21.09.2022

TO : AXA MOTOR CLAIMS DEPTS  
VEHICLE NO : SLV8818Y  
MODEL : TOYOTA VOXY  
DATE OF ACCIDENT : 21.09.2022  
TIME OF ACCIDENT : 09:15 HRS

ZWR800284851

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                   | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-----------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT DOOR LH <i>Dented</i>                   | 1   | \$ 1,675.00     | \$ 1,675.00      |
| 2   | FRONT DOOR OUTER STRIP LH <i>3MP</i>          | 1   | \$ 175.00       | \$ 175.00        |
| 3   | FRONT DOOR WEATHER STRIP LH <i>1MP</i>        | 1   | \$ 279.30       | \$ 279.30        |
| 4   | FRONT DOOR STOPPER LH <i>2</i>                | 2   | \$ 19.80        | \$ 39.60         |
| 5   | FRONT DOOR HINGE (UPPER) LH <i>1MP</i>        | 1   | \$ 80.00        | \$ 80.00         |
| 6   | FRONT DOOR HINGE (LOWER) LH <i>1MP</i>        | 1   | \$ 80.00        | \$ 80.00         |
| 7   | FRONT DOOR INNER LOCK LH <i>3MP</i>           | 1   | \$ 581.70       | \$ 581.70        |
| 8   | FRONT DOOR INNER TRIM LH <i>1MP</i>           | 1   | \$ 1,864.30     | \$ 1,864.30      |
| 9   | FRONT DOOR POWER WINDOW MOTOR LH <i>1MP</i>   | 1   | \$ 647.20       | \$ 647.20        |
| 10  | FRONT DOOR REGULATOR LH <i>3MP</i>            | 1   | \$ 387.60       | \$ 387.60        |
| 11  | FRONT DOOR SPEAKER LH <i>1MP</i>              | 1   | \$ 357.90       | \$ 357.90        |
| 12  | FRONT DOOR BLACK STICKER LH <i>1MP</i>        | 1   | \$ 174.30       | \$ 174.30        |
| 13  | FRONT DOOR FRAME WEATHER STRIP LH <i>1MP</i>  | 1   | \$ 289.80       | \$ 289.80        |
| 14  | SIDE SKIRT LH <i>torn</i>                     | 1   | \$ 1,125.30     | \$ 1,125.30      |
| 15  | SLIDING DOOR LH <i>Dented</i>                 | 1   | \$ 1,585.00     | \$ 1,585.00      |
| 16  | SLIDING DOOR STRIP SENSOR LH <i>Dented</i>    | 1   | \$ 971.50       | \$ 971.50        |
| 17  | SLIDING DOOR OUTER STRIP LH <i>1MP</i>        | 1   | \$ 1,300.00     | \$ 1,300.00      |
| 18  | SLIDING DOOR POWER WINDOW MOTOR LH <i>1MP</i> | 1   | \$ 487.10       | \$ 487.10        |
| 19  | SLIDING DOOR AUTO SYSTEM MOTOR <i>1MP</i>     | 1   | \$ 1,993.90     | \$ 1,993.90      |
| 20  | SLIDING DOOR STICKER (BLACK) (SET) <i>1MP</i> | 1   | \$ 210.00       | \$ 210.00        |
| 21  | SLIDING DOOR FRONT INNER LOCK LH <i>1MP</i>   | 1   | \$ 618.10       | \$ 618.10        |

1598

880.

photo.

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLV8818Y  
 MODEL : TOYOTA VOXY  
 DATE OF ACCIDENT : 21.09.2022  
 TIME OF ACCIDENT : 09::15 HRS

|    |                                                    |   |             |             |   |
|----|----------------------------------------------------|---|-------------|-------------|---|
| 22 | SLIDING DOOR INNER TRIM LH <i>Not rec</i>          | 1 | \$ 1,897.40 | \$ 1,897.40 | + |
| 23 | SLIDING DOOR FRAME WEATHER STRIP LH <i>Not rec</i> | 1 | \$ 577.40   | \$ 577.40   | + |
| 24 | SLIDING DOOR STEP PANEL LH <i>Not rec</i>          | 1 | \$ 633.70   | \$ 633.70   | + |
| 25 | SLIDING DOOR STEP PANEL GARNISH LH <i>Not rec</i>  | 1 | \$ 498.80   | \$ 498.80   | + |
| 26 | SLIDING DOOR WEATHERSTRIP LH <i>Not rec</i>        | 1 | \$ 298.00   | \$ 298.00   | + |
| 27 | SLIDING DOOR BACK INNER LOCK <i>Not rec</i>        | 1 | \$ 524.30   | \$ 524.30   | + |
| 28 | SLIDING DOOR LOWER ROLLER LH <i>Not rec</i>        | 1 | \$ 285.00   | \$ 285.00   | + |
| 29 | SLIDING DOOR LOCK CATCH LH <i>Not rec</i>          | 1 | \$ 78.00    | \$ 78.00    | + |
| 30 | REAR FENDER LH <i>Repis</i>                        | 1 | \$ 850.00   | \$ 850.00   | + |
| 31 | REAR FENDER ARCH SEAL LH <i>?</i>                  | 1 | \$ 138.10   | \$ 138.10   | + |
| 32 | REAR FENDER LOWER GUARD LH <i>Not rec</i>          | 1 | \$ 148.10   | \$ 148.10   | + |
| 33 | REAR FENDER COWLING LH <i>Not rec</i>              | 1 | \$ 158.10   | \$ 158.10   | + |
| 34 | REAR FENDER INNER SHIELD LH                        | 1 | \$ 218.10   | \$ 218.10   | + |
| 35 | REAR FENDER GLASS WITH MOULDING                    | 1 | \$ 930.00   | \$ 930.00   | + |
| 36 | REAR ABS SENSOR LH <i>Not rec</i>                  | 1 | \$ 398.00   | \$ 398.00   | + |
| 37 | REAR SHOCK ABSORBER LH <i>Not rec</i>              | 1 | \$ 395.00   | \$ 395.00   | + |
| 38 | REAR WHEEL HUP WITH BEARING LH <i>Not rec</i>      | 1 | \$ 995.00   | \$ 995.00   | + |
| 39 | REAR AXLE <i>Not rec</i>                           | 1 | \$ 3,150.00 | \$ 3,150.00 | + |
| 40 | REAR BUMPER <i>Not rec</i>                         | 1 | \$ 1,450.00 | \$ 1,450.00 | + |
| 41 | REAR BUMPER SIDE BRACKET <i>Not rec</i>            | 2 | \$ 78.00    | \$ 156.00   | + |
| 42 | REAR BUMPER SIDE RETAINER <i>Not rec</i>           | 2 | \$ 78.00    | \$ 156.00   | + |

541880

4064.10

TOTAL PRICE \$ 28,857.60  
 LESS 25% \$ 7,214.40  
 SUB TOTAL PRICE \$ 21,643.20

| S/N | DESCRIPTION                                           | QTY | UNIT S/NETT | TOTAL S/NETT |   |
|-----|-------------------------------------------------------|-----|-------------|--------------|---|
| 1   | FRONT DOOR INNER TRIM CLIP <i>Not rec</i>             | 1   | \$ 60.00    | \$ 60.00     | + |
| 2   | SLIDING DOOR INNER TRIM CLIP RH (SET) <i>Not rec</i>  | 1   | \$ 60.00    | \$ 60.00     | + |
| 3   | REAR FENDER SEALANT LH <i>Not rec</i>                 | 1   | \$ 80.00    | \$ 80.00     | + |
| 4   | REAR FENDER COWLING CLIP LH (SET) <i>Not rec</i>      | 1   | \$ 50.00    | \$ 50.00     | + |
| 5   | REAR FENDER INNER TRIM CLIP <i>Not rec</i>            | 1   | \$ 60.00    | \$ 60.00     | + |
| 6   | REAR FENDER INNER SHIELD CLIP LH (SET) <i>Not rec</i> | 1   | \$ 30.00    | \$ 30.00     | + |
| 7   | REAR FENDER GLASS SOLAR FILM <i>?</i>                 | 1   | \$ 300.00   | \$ 300.00    | + |
| 8   | REAR FENDER GLASS INNER SEAL <i>Not rec</i>           | 1   | \$ 60.00    | \$ 60.00     | + |
| 9   | REAR FENDER GLASS SEALANT <i>Not rec</i>              | 1   | \$ 80.00    | \$ 80.00     | + |

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLV8818Y  
 MODEL : TOYOTA VOXY  
 DATE OF ACCIDENT : 21.09.2022  
 TIME OF ACCIDENT : 09::15 HRS

|    |                                               |   |             |             |             |
|----|-----------------------------------------------|---|-------------|-------------|-------------|
| 10 | REAR WHEEL TYRE LH <i>Neu</i>                 | 1 | \$ 450.00   | \$ 450.00   | <i>+</i>    |
| 11 | REAR WHEEL RIM LH <i>at</i>                   | 1 | \$ 1,200.00 | \$ 1,200.00 | <i>780.</i> |
| 12 | WHEEL CAP (SET) <i>Not m</i>                  | 1 | \$ 120.00   | \$ 120.00   | <i>+</i>    |
| 13 | REAR BUMPER CLIP (SET) <i>Neu</i>             | 1 | \$ 50.00    | \$ 50.00    | <i>+</i>    |
| 14 | STEP PANEL GARNISH CLIP <i>Neu</i>            | 1 | \$ 60.00    | \$ 60.00    | <i>+</i>    |
| 15 | DOOR CHROME MOULDING (SPECIAL TYPE) <i>at</i> | 1 | \$ 800.00   | \$ 800.00   | <i>450</i>  |
| 16 | DOOR VISOR (SET) <i>Neu</i>                   | 1 | \$ 300.00   | \$ 300.00   | <i>80.</i>  |
| 17 | BRAKE OIL <i>Neu</i>                          | 1 | \$ 30.00    | \$ 30.00    | <i>+</i>    |

*11310*

TOTAL \$ 3,790.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| S/N | JOB DESCRIPTION                                                           | PRICE       | ADJUSTED COST |
|-----|---------------------------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                | \$ 2,200.00 | <i>600.</i>   |
| 2   | TO SPRAY PAINT AFFECTED AREA                                              | \$ 1,600.00 | <i>850.</i>   |
| 3   | TUFF COAT                                                                 | \$ 250.00   | <i>50</i>     |
| 4   | WIRING CHECK                                                              | \$ 150.00   | <i>30</i>     |
| 5   | REMOVE AND REFIX FUEL TANK                                                | \$ 120.00   | <i>x</i>      |
| 6   | TRANSFER FRONT DOOR MECHANISM RH                                          | \$ 80.00    | <i>40</i>     |
| 7   | REMOVE & REINSTALL FRONT WINDOW GLASS RH                                  | \$ 60.00    | <i>40.</i>    |
| 8   | REMOVE AND REFIX REAR FENDER QUARTER GLASS RH                             | \$ 120.00   | <i>x</i>      |
| 9   | REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR | \$ 250.00   | <i>x</i>      |
| 10  | REMOVE AND REFIX REAR UNDERCARRIAGE                                       | \$ 550.00   | <i>80 x.</i>  |
| 11  | TO PRESS REAR WHEEL BEARING                                               | \$ 80.00    | <i>x</i>      |
| 12  | FOUR WHEEL ALIGNMENT                                                      | \$ 120.00   | <i>80.</i>    |

TO : **AXA** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLV8818Y**  
 MODEL : **TOYOTA VOXY**  
 DATE OF ACCIDENT : 21.09.2022  
 TIME OF ACCIDENT : 09::15 HRS

|    |                                                                                                |           |   |
|----|------------------------------------------------------------------------------------------------|-----------|---|
| 13 | TRANSFER SLIDING DOOR MECHANISM RH                                                             | \$ 80.00  | ✓ |
| 14 | REMOVE, REFIX AND RESET SLIDING DOOR AUTO SYSTEM                                               | \$ 350.00 | X |
| 15 | REMOVE & REINSTALL REAR WINDOW GLASS                                                           | \$ 60.00  | X |
| 16 | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 120.00 | X |
| 17 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                           | \$ 80.00  | X |
| 18 | RESET ABS LIGHT                                                                                | \$ 350.00 | X |
| 19 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | X |

**TOTAL \$6,800.00**

TOTAL PARTS COST : \$ 25,433.20  
 TOTAL LABOUR COST : \$ 6,800.00  
 TOTAL REPAIR COST : \$ 32,233.20

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR

IRENE

HP : 8297 9787

*Adrian Cj*  
*h/s 21/09/22*

*04 Days*

*total 7144.10*

*h/s: 5-7K*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: