



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

TEAMWORK GARAGE PTE LTD

Ref: CS/TP22009326/Gny3

53 UBI AVENUE 1 #01-24 SINGAPORE 408934

Date: 21/09/2022

Code: TP376

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	Veh. Inspected	SNF 471B
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From KHIERTHII VT	Assign Date	21/09/2022

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	18/09/2022	Inspection Date	21/09/2022
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--