



Date of Accident : 21 September 2022

1 Defu Lane 6 Singapore 539365
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No. : M2-8922054-2

Miss Chan Choy May (Chen Cuimei)

Date : 22 September 2022

Estimate To Repair SMG7710Y - SUBARU FORESTER 2.0I-L CVT AWD
Chassis No : JF1SJ5KC5JG111941

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>RM</i>	\$ 660.20
02	8 ps	rear bumper clips @ \$4.50 <i>11</i>	\$ 36.00
03	1 pc	rear bumper lower lip <i>11</i>	\$ 650.00
04	1 pc	rear bumper top moulding - aluminium <i>Buf 300</i>	\$ <u>550.00</u>
05	1 pc	rear bumper o/s reflector <i>11</i>	\$ 22.80
06	1 pc	rear bumper beam <i>11</i>	\$ 320.00
07	1 pc	tailgate lid <i>Body</i>	\$ 1,712.80
08	1 pc	tailgate lid lock <i>11</i>	\$ 176.40
09	1 pc	tailgate lid outer garnish <i>300</i>	\$ 222.40
10	1 pc	tailgate lid subaru lettering <i>RM</i>	\$ 70.00
11	1 PC	tailgate lid symmetrical lettering <i>11</i>	\$ 72.00
12	1 PC	tailgate lid AWD lettering <i>RM</i>	\$ 75.00
13	1 PC	tailgate lid forester lettering <i>Dis</i>	\$ 45.00
14	1 PC	tailgate lid sport lettering <i>one</i>	\$ 55.00
15	1 pc	tailgate lid subaru logo <i>11</i>	\$ 88.00
16	1 pc	tailgate weatherstrip <i>11</i>	\$ 120.00
17	1 pc	rear windscreen moulding <i>RM</i>	\$ 125.00
			\$ 5,000.60
		Less 10 % <i>20%</i>	\$ 500.06
			\$ 4,500.54
		<u>SPECIAL NETT ITEMS</u>	
18	1 tube	rear windscreen sealant <i>RM</i>	\$ 80.00
19	1 tube	rear windscreen inner seal <i>RM</i>	\$ 120.00
20	1 set	rear bumper parking sensor <i>11</i>	\$ 450.00
			\$ 650.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 80.00
02		To rust-proofing of the affected areas.	\$ 180.00
03		To remove and refit rear windscreen glass.	\$ 140.00
04		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
05		To reinstall of rear bumper parking sensor.	\$ <i>11</i> 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

SAF Insured's Veh No : 34662MID

Date of Accident : 21 September 2022

Miss Chan Choy May (Chen Cuimei)

Date : 22 September 2022

Estimate To Repair SMG7710Y - SUBARU FORESTER 2.0I-L CVT AWD

Chassis No : JF1SJ5KC5JG111941

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 2,840.00
		Total	\$ 7,990.54

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2605.2
202
2084.16
80
1130
3294.16