

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0816/2022/EQ
DATE : 20-Sep-22
WIP : 42637

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN ZHENG HUI ERNEST
ADDRESS : 460B SENGKANG WEST WAY
#13-105
SINGAPORE 792460
TELEPHONE : HP +65 96956809
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700031645-05
VEHICLE NO : **SJH 9223 D**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 22/7/2017
ENGINE NO : CVN 038994
CHASSIS NO : WAUZZZF4XHA165018
MILEAGE : 55,640
DATE IN : 20-Sep-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Sep-22
PLACE OF ACCIDENT : SELETAR MALL CARPARK EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJH 9223 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,400.00	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	
TOTAL LABOUR CHARGES		: \$ 7,290.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJH 9223 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS FRONT DOOR.	\$ 3,800.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 11,282.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 9223 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
7	RADIATOR GRILLE	1	\$ 1,277.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	
10	FRONT BUMPER REINFORCEMENT BAR	1	\$ 899.00	
11	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
12	FRONT BUMPER BRACKET - RH	1	\$ 254.00	
13	FRONT BUMPER TOP COVER	1	\$ 143.00	
14	CAUTION SIGN STICKER	1	\$ 16.00	
15	AIR CONDITIONER STICKER	1	\$ 9.00	
16	FRONT BUMPER BRACKET	1	\$ 154.00	
17	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
18	HORN LOW TONE - RH	1	\$ 139.00	
19	HORN BRACKET - RH	1	\$ 33.00	
20	FRONT FENDER - RH	1	\$ 861.00	
SUB TOTAL SPARE PARTS		:	\$ 7,793.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 9223 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00	
22	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	
23	FRONT FENDER BRACKET - RH	1	\$ 41.00	
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00	
25	FRONT FENDER RIVET	7	\$ 27.00	
26	FRONT FENDER BRACE - RH	1	\$ 132.00	
27	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 149.00	
29	FRONT WHEEL SPOILER	1	\$ 82.00	
30	FRONT SPOILER - RH	1	\$ 40.00	
31	FRONT WHEEL SPOILER STONE CHIP GUARD	1	\$ 57.00	
32	FRONT FENDER LEDGE COVER - LONG	1	\$ 35.00	
33	FRONT FENDER LEDGE COVER - RH	1	\$ 26.00	
34	BONNET	1	\$ 3,425.00	
35	BONNET ATTACHMENT PARTS	1	\$ 431.00	
36	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	
37	BONNET STRIKER - RH	1	\$ 56.00	
38	BONNET LOCK	1	\$ 228.00	
39	BONNET BOWDEN CABLE	1	\$ 64.00	
40	BONNET RELEASE LEVER	1	\$ 15.00	
SUB TOTAL SPARE PARTS		:	\$ 5,524.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 9223 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT - RH	1	\$ 8,294.00	
42	HEADLIGHT POWER MODULE	1	\$ 842.00	
43	HEADLIGHT CONTROL UNIT	1	\$ 840.00	
44	HEADLIGHT HOSE - RH	1	\$ 42.00	
45	HEADLIGHT COMPENSATING PIECE	3	\$ 137.00	
46	LIFT CYLINDER - RH	1	\$ 231.00	
47	LIFT CYLINDER BRACKET	1	\$ 7.00	
48	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
49	LIFT CYLINDER HOSE	1	\$ 45.00	
50	LOCK CARRIER	1	\$ 1,478.00	
51	LOCK CARRIER SUPPORT - RH	1	\$ 43.00	
52	A/C CONDENSER	1	\$ 683.00	
53	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
54	READY-MIX COOLANT	6	\$ 297.00	
55	RADIATOR AIR GUIDE - RH INNER	1	\$ 32.00	
56	RADIATOR AIR GUIDE - RH OUTER	1	\$ 14.00	
57	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	
58	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00	
59	FRONT NO PLATE	S/N	\$ 60.00	
60	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 26,934.00	
TOTAL LABOUR CHARGES		:	\$ 11,282.00	
GRAND TOTAL		:	\$ 38,216.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT