


Section A - Accident Details

Registration Number	SHB5515T
Case Reference Number	TAX/09/22/2038
Registration Date	12/10/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG SWEE TIONG
Type of Accident	Head to Rear
Accident Date and Time	18/9/2022 4:20 PM
Accident Reported Date and Time	19/9/2022 12:22 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116309
Special Instruction to ARC, if any	TP/REAR PORTION
Prepared Date and Time	19/9/2022 3:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$5,210.86	\$660.16
Total Other Cost	\$680.00	(\$160.16)
TOTAL COST	\$7,304.86	\$900.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	22/09/2022 10:15 AM	22/09/2022 9:58 AM
Signature		
Remarks	Lumpsum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/10/2022

User ID : PohSuan

	5256547900	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
	5256647900	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
	5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.53	Replace	Replace	√
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
	9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	8155147281	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	8158147010	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	8149747020	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
	8149847020	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
	5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
	5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
	6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
	5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
Total				\$6,173.30		\$480.16			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
Total					180.00		180.00		

	660.16	
+	200.00	
+	240.00	L/S \$900/-
	<u>1,100.16</u>	
	-20%	
	<u>880.13</u>	