

Case Details

Case Reference Number : TAX/09/22/2038
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5515T

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19387-ID
 Assigned By : Wei Siong #

Insurance Company Name : income insurance limited
 Accident Date and Time : 18/09/2022 08:20 AM
 Vehicle Age(In Months) :-

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	0	Repair	R
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xan
Standard	Main			PAD, RR BUMPER, CTR	3	2.50	7.50	25.00	5.63	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	1	12.30	12.30	25.00	9.23	Replace	0	0	Not Give	Xan
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, RH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xan
Standard	Main			RETAINER, RR BUMPER, LH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, RH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xan
Standard	Main			SEAL, RR BUMPER, LH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	0	0	Not Give	Xan
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	1	467.63	Replace	de
Standard	Main			FILLER, RR BUMPER, RH	1	168.60	168.60	25.00	126.45	Replace	0	0	Not Give	Xan
Total Spare Part Cost									5,030.86	Surveyor Total		480.15		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									4,024.69	Final Sur Total		384.12		

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			FILLER, RR BUMPER , LH	1	168.00	168.00	25.00	126.45	Replace	0	0	Not Give	Xm
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	16.70	16.70	25.00	12.52	Replace	1	12.52 12.53	Replace	scr
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	Xm
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	25.00	58.50	Replace	0	0	Not Give	Xm
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	1.65	25.00	1.65	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	489.00	489.00	10.00	440.10	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY ASSY , RR BUMPER , RH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xm
Standard	Main			LENS & BODY ASSY , RR BUMPER , LH	1	544.40	544.40	10.00	489.96	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	189.20	189.20	25.00	141.90	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	261.60	261.60	25.00	196.20	Replace	0	0	Not Give	Xm
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0	Not Give	Xm
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0	Not Give	Xm
Total Spare Part Cost									5,030.86	Surveyor Total		480.15		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									4,024.69	Final Sur Total		384.12		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200.00	
Total:			676.00	200.00	

Spray Cost Detail

