



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0320722

Date of Report : 18/08/2022

To : M/s Lucky Joint Construction Pte Ltd

C/o. 48 Toh Guan Road East

#01-119 Enterprise Hub

Singapore 608586

Date of Assignment : 25/07/2022

Report requested by : M/s Lucky Joint Construction

Date of Accident : 19/07/2022

Date of Inspection : 25/07/2022

Claim No. : Third Party Claim

Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : GBD9790Z

Make & Model : Citroen Berlingo LWB 1.6 EHDI ETG

Date of Registration : 06/08/2015

Colour : White

Engine Capacity (cc) : 1560

Mileage (km) : 157727km

Chassis / Frame No. : VF77F9HF8FJ532730

Engine No. : 10JBFR0018231

TYRE CONDITION

Front LH : 4 mm

Make : Green Max

Front RH : 4 mm

Make : Green Max

Rear LH : 4 mm

Make : Green Max

Rear RH : 4 mm

Make : Green Max

Road wheels Type : Standard

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good

Paintwork : Good

Handbrake : Serviceable

Footbrake : Serviceable

Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Gold Autoworks Pte Ltd

48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586

ASSESSMENT

Repairer's Estimate : \$ 14,883.60

Revised Amount : \$ 12,092.50

Less Excess : \$ -

Recommended Reserve : \$ 9,670.00 (Lump Sum)

Estimated Normal Period of Repairs : 12 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : GBD9790Z

Report No. : PAS/TP/0320722

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear RH portion. (The RHF roadwheel was also affected)

DAMAGES

The rear RH door, rear RH door glass, rear bumpers, rear end panel, rear floor panel, RHR chassis member, roof panel, RHR outer body panel, and panel extension, RH taillamp & taillamp panel, RHR pillar inner member, RHR inner wheel house, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$12,092.50.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,670.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : GBD9790Z

Report No. : PAS/TP/0320722

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (S\$)	Our Assessment (S\$)	
1	1 pc	Rr door RH	Dented		\$ 1,780.00	\$ 1,780.00	✓
2	1 pc	Rr door glass RH	Broken		\$ 385.00	\$ 385.00	✓
3	1 pc	Rr door emblem (Logo)	Necessary		\$ 68.00	\$ 68.00	✓
4	1 pc	Rr door emblem (Citroen)	Necessary		\$ 56.00	\$ 56.00	✓
5	1 pc	Rr door emblem (C&C)	Necessary		\$ 23.00	\$ 23.00	✓
6	2 pcs	Rr door hinge RH	Dented/Bent	\$ 154.00	\$ 308.00	\$ 308.00	✓
7	1 pc	Rr door checker RH	Bent		\$ 125.00	\$ 125.00	✗ NN
8	1 pc	Rr door inner trim RH	Deformed		\$ 118.00	\$ 118.00	✓
9	1 pc	Rr door top lock RH	Bent/Jammed		\$ 107.00	\$ 107.00	✓
10	1 pc	Rr door bottom lock RH	Bent/Jammed		\$ 107.00	\$ 107.00	✓
11	1 pc	Taillamp RH	Broken		\$ 148.00	\$ 148.00	✓
12	1 pc	Rr taillamp panel RH	Dented/Distorted		\$ 408.00	\$ 408.00	✓
13	1 pc	Rr pillar inner member RH	Dented/Distorted		\$ 598.00	\$ 598.00	✗ repair
14	1 pc	Rr inner wheel house RH	Dented/Repair		\$ 682.00	\$ -	✗ repair
15	1 pc	Rr body panel inner trim RH	Torn		\$ 182.00	\$ 182.00	✓
16	1 pc	Rr body panel outer extension RH	Dented/Buckler		\$ 521.00	\$ 521.00	✗ repair
17	1 pc	Rr body panel outer RH	Dented/Distorted		\$ 1,253.00	\$ 1,253.00	✓
18	1 pc	Rr bumper	Dented		\$ 584.00	\$ 584.00	✓
19	1 pc	Rr bumper tow cover	Broken/Dislodged/Missing		\$ 23.00	\$ 23.00	✓
20	1 pc	Rr bumper side extension RH	Dented		\$ 263.00	\$ 263.00	✗ NN
21	2 pcs	Rr bumper side guide R/L	RH Dented	\$ 103.00	\$ 206.00	\$ 103.00	✓
22	1 pc	Rr bumper reinforcement	Dented		\$ 381.00	\$ 381.00	✓
23	1 pc	Rr end panel	Dented/Distorted		\$ 413.00	\$ 413.00	✓
24	1 pc	Rr weatherstrip	Torn/Necessary		\$ 171.00	\$ 171.00	✓
25	1 pc	Rr floor panel	Dented/Repair		\$ 752.00	\$ -	✗ repair
26	1 pc	Rr floor panel carpet	Serviceable		\$ 642.00	\$ -	✗ NN
27	1 pc	Roof panel	Dented/Repair			(Refer labour no. 4, 6 & 7)	
28	1 pc	Rr inner wheel house RH	Dented/Repair			(Refer labour no. 4, 6 & 7)	
29	1 pc	Rr floor panel	Dented/Repair			(Refer labour no. 4, 6 & 7)	
30	1 pc	Rr chassis member RH	Dented/Repair			(Refer labour no. 4, 6 & 7)	
					\$ 10,304.00	\$ 8,125.00	
Less Discount : 10%					\$ 1,030.40	10% \$ 812.50	
List Parts Sub-Total :					\$ 9,273.60	\$ 7,312.50	
1	1 pc	Rr door glass sealant RH	Necessary	S/N	\$ 40.00	\$ 40.00	✓
2	1 pc	Rr door sticker (6pax) RH	Necessary	S/N	\$ 20.00	\$ 20.00	✓
3	1 set	Rr reverse sensor	Dented/Damaged	S/N	\$ 200.00	\$ 200.00	✓
4	1 pc	Rr body panel outer sealant RH	Necessary	S/N	\$ 40.00	\$ 40.00	✓
Special Nett Sub-Total :					\$ 300.00	\$ 300.00	
Parts Total :					\$ 9,573.60	\$ 7,612.50	



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : GBD9790Z

Report No. : PAS/TP/0320722

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	\$ 50.00	\$ 30.00 ✓
2	To transfer RH door component parts to new door.	\$ 100.00	\$ 80.00 ✓
3	To install RH rear door glass.	\$ 100.00	\$ 80.00 ✓
4	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. (Include remove roof lining, carpet and supply adhesive glue)	\$ 150.00	\$ 120.00 80 ✓
5	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 50.00	\$ 50.00 30 ✓
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 2,000.00	\$ 1,760.00 1400 ✓
7	To spray painting, blending on affected and adjacent area.	\$ 2,000.00	\$ 1,500.00 800 ✓
8	To supply body sticker film materials such as artwork, logo, etc. and wrap, apply on damaged/affected body.	\$ 800.00	\$ 800.00 600 ✓
9	To check and adjust wheels alignment.	\$ 60.00	\$ 60.00 ✗
Labour Total :		\$ 5,310.00	\$ 4,480.00
Total (Parts & Labour) :		\$ 14,883.60	\$ 12,092.50

For Lump Sum Repairs

10 days

The final adjusted Lump Sum contract amount is \$ 9,670.00

Under normal circumstances, the repairs should be completed within a reasonable period of **12 Working Days**. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

78 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.