Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. From: LKK Auto Consultants Pte Ltd

Ltd. 51 Ubi Ave 1 #01-25 79 Robinson Road #09-01 Paya Ubi Industrial Park

Singapore 068897 Singapore 408933

Attn: Sharon Lim Date: 23 Sep 2022

Preliminary Advice

Vehicle No : SML8057S Accident Date : 02/09/2022

Make : TOYOTA WISH Policy No. :

SP2002211882-

01

Date : 22/09/202

Date of : 22/09/2022 Est. Duration of

Inspection Repair : 6

Inspection At: SUCCESS UNITED PTE LTD (HQ)

2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB

SINGAPORE 417921

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 7,941.20 Revised Amount :S\$ 4,372.50 Check Items (Estimated) :S\$ 1,755.60 Total :S\$ 6,128.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 36,000.00 COE / PARF Rebate :S\$ 9,493.00

Salvage Value :S\$

Margin for Repair :S\$ 26,507.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: THE VEHICLE REPAIR ON LUMP SUM BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.