

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22009339/UNY3Q2**Date:** 05/12/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP305642
Claimant Vehicle No :	SNE385Y	Insured Vehicle No :	SKJ7184Z
Date of Loss:	20/09/2022	Nature of Claim:	TP
		Claim No:	MPC03699

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE385Y		
Make & Model:	TOYOTA ALPHARD, 2.4 (A)	Engine No:	2AR2713639
Reg. Date:	03/11/2021 (Man. Year: 2021)	Chassis No:	AYH300133924
Colour:	White	Odometer:	32313 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,829.10	0.00	2,829.10	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	800.00	470.00	37.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,099.10	800.00	3,299.10	80.48
+ GST 7.00/7.00% (S\$)	286.94	56.00	230.94	80.48
Nett Amount (S\$)	4,386.04	856.00	3,530.04	80.48

INSPECTION

Date of Assignment:	22/09/2022		
Date Inspected:	29/09/2022	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2022)
Parts:	M1-MPV	TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE385Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,288.30 F	*- F
2	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 F	*- F
3	1		*REAR BUMPER SENSOR	Not Necessary	490.80 F	*- F
Total Parts (S\$)						2,829.10 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT ,RENEW ,KNOCKING & WELDING REAR BOOT COVER ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY	New	480.00	300.00
2	SPRAY PAINTING ON DAMAGE PARTS	New	680.00	500.00
3	REMOVE & REFIX REAR BUMPER SENSOR	New	80.00	0.00
4	CHECK ALL LIGHTING AFTER REPAIRS	New	30.00	0.00
Gross Labour Cost (\$)			1,270.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >