

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Lee

Date: 23 Sep 2022

## **Preliminary Advice**

Vehicle No	: SDL3379C	Accident Date	: 18/09/2022
Make	: HONDA ACCORD	Policy No.	: DMPCSNW00062652201
Assignment Date	: 22/09/2022	Excess	: S\$250.00
Date of Inspection	: 22/9/2022	Est. Duration of Repair	: 10
Inspection At	: AUTO INSURE PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,430.33
Revised Amount	:S\$	5,630.33
Check Items (Estimated)	:S\$	1,645.00
Total	:S\$	7,275.33
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	22,836.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,164.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :At the time of inspection, brake and steering in order and all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately 6mm.

Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .