

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FONG MOTORS

1 Kaki Bukit Ave 6 #01-27/45

AutoBay@ Kaki Bukit, Singapore 417883

Tel: 6748 5648, Email: fongmotors@gmail.com

Estimate of Cost of Repairs

Acknowledged by Repairer

Signature:

Date:

Date 12-Oct-2022

Vehicle No. SMZ2677T

Model Suzuki Jimny

CHASSIS/ENG# JSAGJB74V00166404

PARTS

S/N	Item	Quantity	Unit Price	Amount
1	Rear Windscreen Glass <i>Shattered</i>	1	\$983.00	\$983.00 ✓
2	Glass Moulding <i>new</i>	1	\$108.50	\$108.50 ✓
3	Rear Tail Gate <i>Dented</i>	1	\$1,248.00	\$1,248.00 ✓
4	Emblem - Jimny <i>new</i>	1	\$39.80	\$39.80 ✓
5	Emblem - Suzuki <i>new</i>	1	\$39.80	\$39.80 ✓
6	Emblem - All Grip <i>new</i>	1	\$32.80	\$32.80 ✓
7	Tail Gate Hinge Upper <i>new</i>	1	\$105.00	\$105.00 X
8	Tail Gate Hinge Lower <i>new</i>	1	\$105.00	\$105.00 X
9	Spare Tyre Bracket <i>new</i>	1	\$175.00	\$175.00 X
10	Tail Gate Inner Board <i>Dented</i>	1	\$195.00	\$195.00 ✓
11	Tail Gate Absorber <i>new</i>	1	\$78.50	\$78.50 X
12	Wiper Arm <i>new</i>	1	\$69.50	\$69.50 X
13	Wiper Motor <i>Damaged</i>	1	\$395.00	\$395.00 ✓
14	Rear Bumper <i>Dented</i>	1	\$855.00	\$855.00 ✓
15	RH Rear Bumper Lamp <i>cracked</i>	1	\$185.00	\$185.00 ✓
16	RH Rear Lamp Cover <i>crack</i>	1	\$65.00	\$65.00 ✓
17	Tail Gate Lock <i>Damaged</i>	1	\$265.00	\$265.00 ✓
18	Rear No. Plate Garnish <i>Dented</i>	1	\$108.00	\$108.00 ✓
19	Rear No. Plate Lamp <i>new</i>	2	\$28.00	\$56.00 X
20	Rear End Panel <i>Dented</i>	1	\$595.00	\$595.00 ✓
21	Rear Weatherstrip <i>new</i>	1	\$118.50	\$118.50 X
22	Rear Exhaust Pipe <i>Dented</i>	1	\$985.50	\$985.50 795
Sub-total 1				\$6,807.90

NETT ITEMS

S/N	Item	Quantity	Unit Price	Amount
1	Rear No. Plate & Garnish <i>Best</i>	1	\$60.00	\$60.00 ✓
2	Rear Windscreen Glass Sealant <i>new</i>	1	\$60.00	\$60.00 ✓
3	Rear Bumper Climp <i>new</i>	1 Set	\$60.00	\$60.00 30
4	Tail Gate Inner Board Clip <i>new</i>	1 Set	\$60.00	\$60.00 30
5	Reverse Sensor <i>Damaged</i>	1 Set	\$350.00	\$350.00 200
6	Rim <i>new</i>	1	\$1,150.00	\$1,150.00 850

Sub-total 2 \$1,740.00

LABOUR

1	To remove and rear windscreen glass	\$150.00 120
2	To remove and transfer tail gate compartment	\$80.00 80
3	To knock and change parts, LH rooftop	\$1,200.00 1000
4	To spray rear portion and roof top	\$1,200.00 800
5	Tuff kote	\$100.00 80
6	Wiring check	\$80.00 30
7	To remove and refix revers sensor	\$120.00 50
8	To remove and refix exhaust pipe	\$120.00 80
Labour Total		\$3,050.00

Parts & Labour Total \$11,597.90

total: 8493.41
w/s: 6-81C
07 Days.