

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Sep 2022

Preliminary Advice

Vehicle No	: SMR1652M	Accident Date	: 20/09/2022
Make	: TOYOTA CAMRY	Policy No.	: DMPG21014441
Assignment Date	: 22/09/2022	Excess	: S\$0.00
Date of Inspection	: 22/09/2022	Est. Duration of Repair	: 14
Inspection At	: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58 SINGAPORE 408717		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,195.20
Revised Amount	:S\$	20,612.20
Check Items (Estimated)	:S\$	3,721.60
Total	:S\$	24,333.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	56,685.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,315.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.