



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |                             |  |
|--|---|-----------------|-----------------------------|--|
| INDIA INTERNATIONAL INSURANCE PL<br>64 CECIL STREET<br>#05-02 IOB BUILDING SINGAPORE 049711  |   |                 | Ref: CS3/GRB22007302/Tce2-1 |  |
|  |   |                 | Date: 26/09/2022            |  |
|  |   |                 | Code: GRB                   |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                 |                             |  |
| Insured Veh.   | SLQ 6114J   | Veh. Inspected  | FBQ 382J                    |  |
| Policy No.   | D21MFL0000447_01  | Coverage (\$)   | 0.00                        |  |
| Claim No.  | MFL2022D0004049   | Excess (\$)     | 0.00                        |  |
| Assign From  |   | Assign Date     | 25/08/2022                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |                             |  |
| Make & Model   | HONDA CB150   | c.c             | 149                         |  |
| Engine No.   | HIDDEN  | Year of Reg.    | 2019                        |  |
| Chassis No.  | MLHKC2883K5138513   | Colour          | BLACK                       |  |
| Odometer   | -   | Steering        | IN ORDER                    |  |
| Brakes   | IN ORDER  | Modification    | NIL                         |  |
| General  | GOOD  |                 |                             |  |
| <b>3. Conditions of Tyres</b>  |   |                 |                             |  |
|  | Size  | Make            | Balance                     |  |
| R/H Front Tyre   | 110/70 R17  | BRIDGESTONE     | 5 mm                        |  |
| L/H Front Tyre   |   |                 | mm                          |  |
| R/H Rear Tyre  | 140/70 R17  | BRIDGESTONE     | 5 mm                        |  |
| L/H Rear Tyre  |   |                 | mm                          |  |
| <b>4. Description of Damages</b>   |   |                 |                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.<br>DAMAGES SEE DETAILS.   |   |                 |                             |  |
| <b>5. General Information</b>  |   |                 |                             |  |
| Accident Date  | 27/07/2022  | Inspection Date | 02/08/2022                  |  |
| Survey held at   | GP SERVICE PTE LTD<br>282 MACPHERSON ROAD<br>SINGAPORE 348607 |                 |                             |  |
| <b>5a. Remarks</b>   |   |                 |                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                             |  |
| <b>5b. Estimate Days of Repair</b>   |   |                 |                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   |                 | <b>4 Working Days</b>       |  |