

ASS. REC. BY: Tang JHREF: CS3/ASU 21009749/T19

y3-1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. S1M03133

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 945K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP' PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: STQ8116P Yr Regn: 2009 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios c.c. 1497Colour Red A/C: Insured / Std / NI / NASp. Reading 110081 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR055H99305111487

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 12/9/21 @ 530pmSurvey held at Garage 13

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Range: \$14K - \$16K. 15 days

01/10/21 @ 3.01pm revised to Janice Koh via Smart Claims

01/10/21 Submit PRS.

16/12/22 Submit LS \$21700, 15 days (Red \$5600, 21%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 16/12 Typist

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 15

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format: TP/IP/00007/2022Lump Sum 112600 21700