



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302441

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 18/04/2023
Reference CC6/CTI22009362/Aya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLT 3773K
Insured Veh. XE 599D
Claim No. SNM22D206787/C02
Policy No. DMCVSNW00057582200
Accident Date 21/09/2022
Inspection Date 22/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22009362/Aya3q2 Date: 18/04/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 599D	Veh. Inspected	SLT 3773K	
Policy No.	DMCVSNW00057582200	Coverage (\$)	0.00	
Claim No.	SNM22D206787/C02	Excess (\$)	0.00	
Assign From		Assign Date	22/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31253172	Colour	BLACK	
Odometer	86387 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2022	Inspection Date	22/09/2022	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3773K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	840.00	745.00
2	REAR BUMPER O/S & N/S TOP GARNISH	NOT NECESSARY	586.40	-
2	REAR BUMPER O/S & N/S REFLECTOR	NOT NECESSARY	208.00	-
2	REAR BUMPER O/S & N/S RETAINER	NOT NECESSARY	125.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	611.90	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	150.00	-
1	REAR O/S TAIL LAMP PANEL	NOT NECESSARY	213.00	-
2	REAR O/S & N/S TAIL LAMP	CUT	940.00	940.00
1	REAR TAIL GATE	DISTORTED	1,178.00	1,100.00
1	REAR TAIL GATE WEATHERSTRIP	NOT NECESSARY	265.00	-
1	REAR TAIL GATE 'HONDA' EMBEM	NECESSARY	55.00	55.00
1	REAR TAIL GATE 'VEZEL' EMBEM	NECESSARY	55.00	55.00
1	REAR TAIL GATE 'HYBRID' EMBEM	NECESSARY	54.50	54.50
1	REAR TAIL GATE MOULDING	CRACKED	360.50	360.50
1	REAR TAIL GATE INNER TRIM	DEFORMED	310.00	310.00
2	REAR O/S & N/S TAIL GATE INNER TRIM	NOT NECESSARY	87.00	-
1	REAR TAIL GATE LOCK (UPPER)	DAMAGED	260.60	260.60
1	REAR POWER WINDOW MOTOR	NOT NECESSARY	460.30	-
1	REAR TAIL GATE LOCK (LOWER)	NOT NECESSARY	130.00	-
2	REAR TAIL GATE O/S & N/S REFLECTOR	O/S CRACKED	845.60	422.80
1	REAR BUZZER	NOT NECESSARY	210.00	-
2	REAR REGN NO PLATE LAMP	NOT NECESSARY	230.40	-
	LESS 20% DISCOUNT		-1,635.24	-860.68
			6,540.96	3,442.72
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
2	REAR BUMPER SCREW CLIPS (SN)	NOT NECESSARY	20.00	-
2	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
2	REAR O/S & N/S TAIL LAMP CLIPS (SN)	NECESSARY	20.00	20.00
6	REAR TAIL GATE MOULDING CLIPS (SN)	NECESSARY	48.00	20.00

Report Ref No. CC6/CTI22009362/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
12	REAR TAIL GATE INNER TRIM CLIPS (SN)	NECESSARY	34.00	34.00
12	REAR O/S & N/S TAIL GATE INNER TRIM CLIPS (SN)	NOT NECESSARY	34.00	-
4	REAR WINDSCREEN MOULDING (SN)	NECESSARY	145.00	145.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	680.00	-
1	REAR REGN NO PLATE (SN)	NOT NECESSARY	80.00	-
1	REAR REGN NO PLATE BRACKET (SN)	NOT NECESSARY	30.00	-
			1,471.00	519.00
	LABOUR			
	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING .INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,400.00	600.00
	TO SPRAY PAINTING.		1,000.00	600.00
	TO REFIT REAR WINDSCREEN .		150.00	120.00
	TO REMOVE & REPLACE REAR REVERSE SENSOR .		50.00	50.00
	TO CHECK FOR FAULT CODE & RESET ELECTRICAL SYSTEM.	NOT NECESSARY	380.00	-
	TO CHECK WIRING .		120.00	30.00
	TO RE-SEAL ANTI RUST.		200.00	60.00
			3,300.00	1,460.00
GRAND TOTAL			11,311.96	5,421.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC6/CTI22009362/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 3773K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLT 3773K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

