

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 09/11/2022

User ID                      PohSuan

**Section A - Accident Details**

Registration Number	SHD6021J
Case Reference Number	TAX/09/22/2044
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	SHAHRU DIN BIN MOHD SAID
Type of Accident	Head to Rear
Accident Date and Time	20/9/2022 2:55 PM
Accident Reported Date and Time	21/9/2022 11:00 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116331
Special Instruction to ARC, if any	TP/ REAR PORTION/ INCOME - LKK
Prepared Date and Time	22/9/2022 9:01 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$3,050.00	\$500.00
Total Spare Part Cost	\$10,182.81	\$898.97
Total Other Cost	\$620.00	\$40.00
<b>TOTAL COST</b>	<b>\$14,697.81</b>	<b>\$1,738.97 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	9.0	4.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>26/09/2022 9:55 AM</b>	<b>26/09/2022 9:16 AM</b>
Signature		
Remarks	Initial 7 days / sup 2 days / total 9 days	part by part / Resurvey before paint / Before paint photos , After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2210-0112	<b>Invoice Number</b>	
<b>Quotation Date</b>	11.10.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR REAR PORTION	\$845.00	\$300.00
<b>Total Labour</b>	<b>\$845.00</b>	<b>\$300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
RESPRAY WHEEL CAP	\$180.00	\$0.00
TO RESPRAY REAR DOOR LH	\$378.00	\$0.00
RESPRAY MIRROR COVER LH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
RESPRAY MIRROR COVER LH	\$80.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$3,050.00</b>	<b>\$500.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$620.00</b>	<b>\$40.00</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace
		52023-47030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check
		52462-47130	PAD, RR BUMPER, RH & LH , 3	1.00	\$12.00	25.00	\$9.00	Replace	Replace
		52462-47030	PAD, RR BUMPER, RH & LH , 2	1.00	\$4.30	25.00	\$3.23	Replace	Replace
		52462-47020	PAD, RR BUMPER, RH & LH , 1	1.00	\$4.30	25.00	\$3.23	Replace	Replace
		52576-47060	RETAINER, RR BUMPER, LH	0.00	\$143.60	0.00	\$0.00	Replace	Not Given

✓ de  
 X nn  
 ✓ nec  
 ✓ nec  
 ✓ nec  
 X nn

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/11/2022

User ID : PohSuan

		52592-47080	SEAL, RR BUMPER , LH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given	X nn
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√ nec
		52453-47900	GUARD, RR BUMPER, LOWER	1.00	\$405.00	25.00	\$303.75	Replace	Replace	√ de
		81920-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1.00	\$42.20	25.00	\$31.65	Replace	Replace	√ scr
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Check	X nn
		67005-47530	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$1,238.40	0.00	\$0.00	Replace	Not Given	X nn
		76801-47170-A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-STRIDES LOGO	1.00	\$992.30	100.00	\$0.00	Replace	Repair	R
				1.00	\$7.80	0.00	\$7.80	Replace	Replace	√ nec
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√ nec
		75441-47220	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√ nec
		75442-47200	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√ nec
		67004-47211	PANEL SUB-ASSY, REAR DOOR , LH	0.00	\$1,401.70	0.00	\$0.00	Replace	Not Given	X nn
		4261147450	WHEEL, DISC	0.00	\$2,036.30	0.00	\$0.00	Replace	Not Given	X nn
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X nn
		42602-47251	CAP SUB-ASSY, WHEEL	0.00	\$229.00	0.00	\$0.00	Replace	Not Given	X nn
		87940-47440	MIRROR ASSY, OUTER REAR VIEW , LH	0.00	\$1,454.40	0.00	\$0.00	Replace	Not Given	X nn
		87945-47060-A1	COVER, OUTER MIRROR, LH	0.00	\$117.80	0.00	\$0.00	Replace	Not Given	X nn
		58399-47030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Check	X nn
		66259-47010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X nn
		81561-47471	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$367.30	0.00	\$0.00	Replace	Check	X nn
		81498-47040	COVER, REAR COMBINATION LAMP, LH	0.00	\$75.90	0.00	\$0.00	Replace	Not Given	X nn
		81555-47470	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP,	0.00	\$56.70	0.00	\$0.00	Replace	Not Given	X nn
		81456-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Check	X nn
		81590-47070	LAMP ASSY, REAR, LH	0.00	\$317.80	0.00	\$0.00	Replace	Not Given	X nn
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X nn
		58307-47100	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X nn
<b>Total</b>					<b>\$12,579.24</b>		<b>\$898.97</b>			

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		42602-47251	CAP SUB-ASSY, WHEEL	1.00	\$229.00	25.00	\$0.00	Replace	Not Given	X nn
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$0.00	Replace	Not Given	X nn
<b>Total</b>					<b>346.80</b>		<b>0.00</b>			

898.97  
+ 300.00  
+ 540.00  

---

1,738.97