



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M03O26

Date: 05th Oct 2022

Our Ref: CS3/ASM21012645/Tvy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Teo Kitty

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PD 898R

INSURED VEHICLE: SHD 7237Y

ACCIDENT DATE: 09/12/2021

We thank you for your instruction on 22/09/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PD 898R from M/s C L Appraisar Pte Ltd.
- b) Singapore Accident Statement of Vehicles PD 898R and SHD 7237Y.
- c) Final Repair Bill of PD 898R from M/s Best Auto K Pte Ltd.
- d) Colour damaged vehicle photographs of PD 898R.

Pre-Repair Inspection Date: 14/12/2021 at M/s Best Auto K Pte Ltd, 10 Kaki Bukit Rd 2 #03-01, Singapore 417868.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PD 898R
Make & Model	: Mercedes Benz V220D Extra-Long AT
Year of Registration	: 2019
Chassis Number	: WDF44781523665628
Engine Capacity	: 2143 cc

- 2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.