



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE			Ref: CC4/ASM22009381/Upa3q2 Date: 03/04/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SHD 3719A	<b>Veh. Inspected</b>	SNE 7619C	
<b>Policy No.</b>	P2465679	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	S2M04BBW	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>		<b>Assign Date</b>	23/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA CAMRY HYBRID (A)	<b>c.c</b>	2487	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2022	
<b>Chassis No.</b>	JTNB23HK503112944	<b>Colour</b>	GREY	
<b>Odometer</b>	2003 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	215/55 R17	MICHELIN	9 mm	
<b>L/H Front Tyre</b>	215/55 R17	MICHELIN	9 mm	
<b>R/H Rear Tyre</b>	215/55 R17	MICHELIN	9 mm	
<b>L/H Rear Tyre</b>	215/55 R17	MICHELIN	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	19/09/2022	<b>Inspection Date</b>	23/09/2022	
<b>Survey held at</b>	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	