

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) ___ \$ + RS. ___ \$

) Photos

) Others

TOTAL

K LEE AUTOMOTIVE PTE.LTD

48hr

Not Authorized

see

23/09/22

2/5 \$7000

5 days

1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

SHD3719A

ESTIMATE

VEHICLE NO : SNE7619C
MAKE/MODEL : TOYOTA CAMRY
ACC DATE : 19.09.2022

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR BOOT LID 22/Buf	1,275.23	1,275.23 ✓
2	1 REAR BOOT LOGO 111	126.60	126.60 ✓
3	1 REAR BOOT EMBLEM 'TOYOTA' 111	89.20	89.20 ✓
4	1 REAR BOOT EMBLEM 'HYBRID' 111	121.55	121.55 ✓
5	2 REAR BOOT LAMPS -R/L 11	534.12	1,068.24 x
6	1 REAR BOOT OUTER MOULDING 11	284.43	284.43 x
7	1 REAR BOOT INNER LOCK Buf/111	609.87	609.87 ✓
8	1 REAR BOOT INNER TRIM 11	441.59	441.59 x
9	10 REAR BOOT INNER TRIM CLIPS 11	6.50	65.00 x
10	1 REAR BOOT LOCK STICKER 11	89.95	89.95 x
11	1 REAR BOOT W/STRIP 111	311.42	311.42 ✓
12	2 REAR BOOT HINGES -R/L 11	151.60	303.20 x
13	2 REAR BOOT HINGES COVER 11	110.20	220.40 x
14	2 REAR BOOT STOPPER 11	12.60	25.20 x
15	1 REAR BUMPER 111	702.13	702.13 ✓
16	1 REAR BUMPER DIFUSSER 111	451.78	451.78 ✓
17	2 REAR BUMPER REFLECTOR -R/L 111	86.65	173.30 ✓
18	4 REAR BUMPER PDC SENSOR 111	413.71	1,654.84 111
19	2 REAR BUMPER PDC SENSOR HOLDER 111	68.55	137.10 ✓
20	1 REAR BUMPER PDC SENSOR WIRE HARNESS 111	441.90	441.90 x
21	1 REAR BUMPER SPONGE 111	180.14	180.14 ✓
22	1 REAR BUMPER REINFORCEMENT 111	745.89	745.89 ✓
23	2 REAR BUMPER SIDE RETAINERS -R/L 111	110.25	220.50 ✓
24	1 REAR END PANEL 111	978.90	978.90 ✓
25	1 REAR END PANEL GARNISH 111	617.09	617.09 ✓
26	1 REAR EXHAUST SILENCER 111	981.60	981.60 x
27	1 REAR EXHAUST CHROME TRIM 111	241.50	241.50 ✓
28	1 REAR EXHAUST INSULATOR 111	181.92	181.92 x
29	1 REAR FLOOR BOARD 111	565.09	565.09 x
30	1 REAR FLOOR PANEL 111	991.50	991.50 x
31	1 REAR FLOOR PANEL UNDERCOVER 111	454.17	454.17 ✓
32	2 REAR TAILLAMPS -R/L 111	797.45	1,594.90 111
33	1 REAR SMART KEYLESS ANTENNA 111	180.95	180.95 x
			16,527.08
		LESS 25%	4,131.77
		TOTAL	12,395.31

T K LEE AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>SPECIAL NETTS ITEM</u>			
1	1 (SET) REAR BUMPER CLIP	45.00	✓
2	1 (SET) REAR FLOOR PANEL UNDERCOVER CLIP	45.00	✓
3	1 REAR REVERSE CAMERA	550.00	X
			640.00
<u>LABOUR CHARGES :</u>			
1	TO CHECK REAR WIRING	80.00	20
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	120.00	80
3	TO REMOVE & REPLACE EXHAUST SYSTEMS	100.00	X
4	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	80.00	50
5	TO TUFF KOTE	80.00	60
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,200.00	1000
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	1,200.00	800
TOTAL			2,860.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 15,895.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-9061-24
252
6795.93
90
2010
8895.93
252
7116