

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009383/UNY3Q2**Date:** 06/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00189642101

Claimant Vehicle No : SLN67S **Insured Vehicle No :** SJA9696J

Date of Loss: 21/09/2022 Nature of Claim: TP Claim No: SNM22D206773/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN67S**

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN041757

Reg. Date: 25/08/2017 (Man. Year: 2017) Chassis No: WAUZZZF45HN072013

Colour: Blue Odometer: 71012 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,939.40	4,160.20	779.20	15.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	790.00	650.00	45.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,379.40	4,950.20	1,429.20	22.40
Approved Total (Overridden) (\$\$)		4,200.00		
(\$\$)	6,379.40	4,200.00	2,179.40	34.16
+ GST 7.00/7.00% (\$\$)	446.56	294.00	152.56	34.16
Nett Amount (\$\$)	6,825.96	4,494.00	2,331.96	34.16

INSPECTION

Date of Assignment: 23/09/2022

Date Inspected: 23/09/2022 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2022)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN67S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut / Deformed	2,607.00 FL	*2,607.00 FL
2	1		*REAR BUMPER LOWER	Deformed	276.00 FL	*276.00 FL
3	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	105.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR O/S	Cracked	98.00 FL	*98.00 FL
5	1		*REAR BUMPER BEAM	Repair	631.00 FL	*- FL
6	1		*TAILLAMP O/S	Cracked	1,135.00 FL	*1,135.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
8	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,182.00	4,366.00
- List Item Discount on L Items 5.00/5.00% (\$)	242.60	205.80
Total Parts (\$)	4,939.40	4,160.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX UPHOLSTERY	New	100.00	0.00
4	TO SPRAY RUST PROOFING	New	50.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	480.00	320.00
6	TO PUTTY & SPRAY PAINTING	New	680.00	400.00
Gross Labour Cost (\$)			1,440.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >