



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD ALLIANZ
Policy No:	SPCM1000000913	Date of Loss:	11/09/2022
Vehicle Reg. No.:	YQ3990L	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MANDAI LINK LOGISTICS PTE LTD		
Driver:	HII PENG LEE		

Make/Model:	MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (CBU) (M)	Vehicle Reg. Date:	27/05/2021
Vehicle Colour:	WHITE	Chassis No:	FEB71EA30141
Engine No:	4P10D82592		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

*Not Authorized
Penalty B4 paint
Ex @ 900k*

Present Location: CHENG HOE MOTOR PTE LTD (WOODLANDS)

7 days

COST OF CLAIMS

	Amount
Parts	6,806.80
Miscellaneous Items	20.00
Labour	2,280.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,106.80
+ GST 7.00% (\$\$)	637.48
Nett Amount (\$\$)	9,744.28

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Acknowledged by repairer
Signature:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Sep 2022)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

YQ3990L
OD/Al/2022
M2
Canter

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	R ₂ 0.00	0.00	*490.00 F ✓
2	1		*1 PC FRT BUMPER LH SIDE PAD	MT 0.00	0.00	*180.00 F ✓
3	1		*1 PC FRT BUMPER LH BRACKET	R ₂ 0.00	0.00	*98.00 F ✓
4	1		*1 PC FRT BUMPER LH STAY	R ₂ 0.00	0.00	*85.00 F ✓
5	1		*1 PC FRT BUMPER RH BRACKET	R ₂ 0.00	0.00	*98.00 F ✓
6	1		*1 PC FRT GRILLE	CM 0.00	0.00	*550.00 F ✓
7	1		*1 SET FRT GRILLE CLIP	R ₂ 0.00	0.00	*24.00 F ✓
8	1		*1 PC LH SIGNAL LAMP	R ₂ 0.00	0.00	*150.00 F ✓
9	1		*1 PC LH HEADLAMP		0.00	*280.00 F ?
10	1		*1 PC FRT LH CORNAL GARNISH	CM 0.00	0.00	*120.00 F ✓
11	1		*1 PC FRT PANEL	R ₂ 0.00	0.00	*520.00 F ✓
12	1		*1 PC FRT WIPER GARNISH	WAP 0.00	0.00	*195.00 F ✓
13	1		*1 PC FRT WINDSCREEN RUBBER	W 0.00	0.00	*200.00 F ✓
14	1		*1 PC FRT LH SIDE MIRROR ROUND	MT 0.00	0.00	*45.00 F ✓
15	1		*1 PC FRT LH SIDE MIRROR SQUARE BACK COVER	MT 0.00	0.00	*28.00 F ✓
16	1		*1 PC AIRCON EVAPORATOR	100% CM 0.00	0.00	*1,650.00 F ?
17	1		*1 PC CABIN FRT LH MOUNTING		0.00	*395.00 F ?
18	1		*1 PC CABIN FRT MOUNTIN CROSS BAR		0.00	*380.00 F ?
19	1		*1 SET AIRCON HEATER PIPE		0.00	*160.00 F ?
20	1		*1 PC HORN	OD 0.00	0.00	*55.00 F ✓
21	1		*1 PC AIRCON GAS DISCHARGE HOSE		0.00	*150.00 F ?
22	1		*1 PC AIRCON GAS RECEIVER HOSE		0.00	*165.00 F ?
23	1		*1 PC BRAKE OIL PIPE		0.00	*170.00 F ?

F=Franchise part.

Sub Total (\$\$) 6,188.00
+ Margin on L,N Items 10.00% (\$\$) 618.80
Total Parts (\$\$) 6,806.80

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.

Generated using Merlmen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 PC FRT NO. PLATE	
2	1	1 PC FRT NO. PLATE	R ₂ 20.00 ✓
Sub Total (\$\$)			20.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.

Generated using Merlmen e-Claims IEAS

No Particulars

Lab.Type

Amount

Labour Items

1	1) TO REMOVE AND REFIX FRT WINDSCREEN GLASS	New	100.00	✓
2	2) TO REMOVE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS	New	100.00	✓
3	3) TO REMOVE AND REFIX DASH BAORD, METER ASSY AND CHECK WIRING	New	280.00	25.
4	4) TO PANEL BEATING INCLUDE STRAIGHTEN FRT LH WS PILLAR AND RE-ALIGN CABIN POSITION	New	800.00	
5	5) TO PUTTY AND RESPRAY ON FRT PANEL, FRT CORNAL PANEL, FRT GRILLE, BUMPER, BRACKET , FRT LH WS PILLAR	New	700.00	800.00

Gross Labour Cost (\$\$)

2,280.00

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledged by Repairer