



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22009385/Gqy3m4 Date: 05/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 5128G	Veh. Inspected	SMT 3447R	
Policy No.	GA362234	Coverage (\$)	0.00	
Claim No.	S2M04BJ1	Excess (\$)	0.00	
Assign From	LOW GARNET	Assign Date	23/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 2.0	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8K7BA049245	Colour	YELLOW	
Odometer	187917 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40ZR18	TOURADOR	6 mm	
L/H Front Tyre	245/40ZR18	TOURADOR	6 mm	
R/H Rear Tyre	245/40ZR18	TOURADOR	6 mm	
L/H Rear Tyre	245/40ZR18	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2022	Inspection Date	23/09/2022	
Survey held at	2 KAKI BUKIT AVENUE 2 #02-31 KAKI BUKIT AUTOHUB			
Repairer	CHENG CHUAN MOTOR SERVICES			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	