

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 23.09.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLP8073K
MODEL : SEAT LEON
DATE OF ACCIDENT : 22.09.2022
TIME OF ACCIDENT : 07:55 HRS

VSSZ225F2GR223538

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE TOP LOCK <i>3M</i>	1	\$ 537.50	\$ 537.50
2	TAILGATE LOWER LOCK <i>1pc</i>	1	\$ 40.75	\$ 40.75
3	TAILGATE WEATHESTRIIP <i>new</i>	1	\$ 378.16	\$ 378.16
4	TAIL LAMP <i>2H included</i>	2	\$ 467.80	\$ 935.60
5	REAR BUMPER (UPPER) <i>Replaced</i>	1	\$ 1,650.00	\$ 1,650.00
6	REAR BUMPER LOWER CENTER <i>Replaced</i>	1	\$ 476.00	\$ 476.00
7	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 78.00	\$ 156.00
8	REAR BUMPER CENTER BRACKET <i>included</i>	1	\$ 189.00	\$ 189.00
9	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 65.00	\$ 130.00
10	REAR BUMPER SIDE BRACKET JOINT <i>new</i>	2	\$ 79.00	\$ 158.00
11	REAR BUMPER REINFORCEMENT <i>Replaced</i>	1	\$ 768.00	\$ 768.00
12	REAR BUMPER SENSOR <i>2 pieces damaged</i>	2	\$ 256.00	\$ 512.00
13	REAR BUMPER SENSOR HOLDE <i>new</i>	4	\$ 48.00	\$ 192.00
14	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 435.00	\$ 435.00
15	REAR BUMPER LOWER INNER COVER GARNISH <i>included</i>	1	\$ 215.00	\$ 215.00
16	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 85.00	\$ 170.00
17	REAR FENDER INNER TRIM <i>new</i>	2	\$ 364.00	\$ 728.00
18	REAR END PANEL <i>Replaced</i>	1	\$ 968.00	\$ 968.00
19	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 237.00	\$ 237.00
20	REAR EXHAUST ISULATOR <i>new</i>	1	\$ 241.00	\$ 241.00

TOTAL PRICE \$ 9,117.01
LESS 10% \$ 911.70
SUB TOTAL PRICE \$ 8,205.31

5367.80
4831.02

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>included</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (UPPER) (SET) <i>new</i>	1	\$ 30.00	\$ 30.00

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLP8073K
 MODEL : SEAT LEON
 DATE OF ACCIDENT : 22.09.2022
 TIME OF ACCIDENT : 07:55 HRS

3	REAR BUMPER LOWER CENTER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
4	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	10
5	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	8.
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	1
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
			TOTAL	\$ 440.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	500
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 3,720.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,645.31
 TOTAL LABOUR COST : \$ 3,720.00
 TOTAL REPAIR COST : \$ 12,365.31

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF THE REPAIRS THE FOLLOWING AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

- To resurvey before repair painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Adrian Lij
h/s 22/09/22
04hrs

total: 6301.02
h/s SIC

(5K)