

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# YN7814C

Accident Date : 13/9/22

Location : BARTLEY ROAD

Model:

mit fuso
30/5/2015

3P: GBE994G (CHINA TAIPING)

7P Chm. FM65FMA2022
Xiao Tong

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front o/s head lamp <i>Crackd</i>	1,450.60	940	
2	1 pc	Front o/s signal lamp <i>Crackd</i>	665.60	386	
3	1 pc	Front bumper <i>Best</i>	2,585.40	1109	
4	1 pc	Front bumper o/s garnish <i>Missing</i>	300.00	✓	
5	1 pc	Front bumper o/s bracket <i>3 new</i>	340.60	+	
6	8pcs	Front bumper o/s bracket screw <i>new</i>		80.00	+
7	1 pc	Front bumper o/s corner garnish <i>new</i>	110.00	+	
8	1 pc	Front o/s door lamp <i>Crackd</i>	300.00	230	
9	1 pc	Front o/s door sticker <i>new</i>		400.00	200
10	1 pc	Front o/s wheel arch <i>Del'd</i>	550.00	✓	
11	1 pc	Front o/s step aluminium <i>lot</i>	310.00	✓	
12	1 pc	Front o/s step bracket <i>3 new</i>	910.40	+	
13	1 pc	Front o/s step garnish	856.40	+	
14	1 pc	Front o/s step garnish reflector <i>new</i>	120.00	+	
		Sub-Total:	8,499.00	480.00	0.00
			25%	0%	0%
		After Less %:	6,374.25	480.00	0.00
		Labour			
1		To remove and replace front damage parts	1,000.00	400	
2		To spray painting.	1,000.00	600	
3		To check wiring.	100.00	30	
		Sub-Total:	2,100.00		
		Total:	8,954.25		
		After Less 20%:	7,163.40		

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: S T K R
Date:

24 hr accident call

Mobil 1



total: 4088.75
L/s: 3.2K