

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009395/KPA3Q2**Date:** 02/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900148138
Claimant Vehicle No :	SMY7730U	Insured Vehicle No :	SMN6899G
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	3133656653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY7730U	Engine No:	2ZR2H29013
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU70J060219
Reg. Date:	25/03/2021 (Man. Year: 2020)	Odometer:	130788 km
Colour:	Metallic Beige		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,472.57	1,362.02	1,110.55	44.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	860.00	320.00	27.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,652.57	2,222.02	1,430.55	39.17
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	3,652.57	1,750.00	1,902.57	52.09
+ GST 7.00/7.00% (S\$)	255.68	122.50	133.18	52.09
Nett Amount (S\$)	3,908.25	1,872.50	2,035.75	52.09
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,239.95		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment:	22/09/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	22/09/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	2.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	549.70 FL	*549.70 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	144.60 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	144.60 FL	*- FL
4	1		*REAR BUMPER REFLECTOR LH	Serviceable	62.80 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	62.80 FL	*- FL
6	1		*REAR BUMPER LOWER GARNISH	Dented	726.10 FL	*726.10 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	206.90 FL	*206.90 FL
8	1		*REAR END PANEL	Repair	696.20 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	196.40 FL	*- FL
10	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*REAR BUMPER REVERSE SENSOR	Scratched	300.00 FS	*200.00 FS
13	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,170.10	1,732.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	697.53	370.68
Total Parts (\$\$)	2,472.57	1,362.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST AT ACCIDENT AREA	New	500.00	400.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREA	New	500.00	400.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	10.00
Gross Labour Cost (\$)			1,180.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >