FASTECH AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883

Tel No: 67452063/67467158 Fax No: 67458520

Tax Reg No: 200006262D

Not Authorish ren 23/09/22 1/5 & 3400 5 days.

VEH	ICLE	No:	GBF	2720L
-----	------	-----	------------	-------

N I	_	 1-	rr	M
IM	_	 	ı -	11//1

1PC	REAR TAILGATE	DO Sent	1482-50	\$1,860.00
2PCS	REAR TAILGATE LOCK LATCHS @	0\$380.00	105.70	\$760.00
2PCS	REAR TAILGATE LOCK LOWER 'L		1	\$360.00
			440000	
2PCS	REAR TAILGATE LOCK LOWER "L		\$120.00	\$240.00 🗴
1PC	REAR TAILGATE 'DYNA' STICKER		4-8-6,2	_\$80.00
2PCS	TAILLAMPS @\$450.00	Mscre	245-10	\$900.00 () (
2PCS	TAILLAMP HOUSING PANELS @:	\$180.00 NSSCH	166.00	\$360.00 126
1PC	REAR LICENCE PLATE BRACKET	Sert	110.65	\$345.00
1PC	REAR EXHAUST	11		\$1,250.00 ×
1PC	REAR EXHAUST MOUNTING	10		\$85.00 🗡
1PC	REAR LOWER MEMBER	2ut	485.10	\$685.10
1PC	REAR CROSS MEMBER	R		\$680.00 ×
1PC	DROPSIDE GATE PANEL A/S	2	1/12 25%	\$2,290.00 📈
	••		110.	\$9,895.10

S.NETT

TO CLIECK MUDINIC

1PC	REAR TAILGATE INNER ALUMINIUM PLATE	But/00	\$900.00 480
1SET	REAR TAILGATE '70km/h & 13pax STICKER	ner,	\$50.00 20
1SET	REAR REVERSE SENSOR	Shorhl	\$300.002
1PC	REAR LICENCE PLATE	Bert	\$300.00 200
1SET	REAR ALUMINIUM PLATE RIVET	nei	\$100.00 33
1SET	REAR LOWER STEP BAR	suf	\$600.00300
1PC	REAR STEP BRACKET	R	\$200.00 🗴
			= -

TO CHECK WIRING		\$50.00 20
TO DISMANTLE & REPLACED REVERSE SENSOR		\$100.00
TO DISMANTLE & REPLACED REAR CARGO DECK	1-	1 \$800.00 丈
TO STRAIGHTEN & REALIGN CHASSIS	1-	√ \$1,000.00 X
TO SPRAY RUST PROOFING		\$200.00
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$1,500.00 600
TO PUTTY & SPRAY PAINTING		\$1,500.00 600
	TOTAL	\$17,245.10

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1910.96 1910.96