



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22009398/Evy3m4 Date: 03/10/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 869E	Veh. Inspected	SHD 2049G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/09/22/2050	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	23/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	AYH300077810	Colour	WHITE	
Odometer	36129 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R16	DUNLOP	4 mm	
L/H Front Tyre	215/50 R16	DUNLOP	4 mm	
R/H Rear Tyre	215/50 R16	DUNLOP	4 mm	
L/H Rear Tyre	215/50 R16	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2022	Inspection Date	23/09/2022	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	