



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 23.09.2022

Strides Taxis Pte Ltd
60 Woodlands Industrial Park E4
Singapore 757705

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2049G TOYOTA VELLFIRE HYBRID 2.5X CVT
(REG DATE : 31 MAR 2022)

To Supply

1) 1pc	Rear bumper	✓	00	\$	1,627.59
Sub total parts					\$ 1,627.59
Less: 25% discount					\$ 406.90
					\$ 1,220.69 ✓

To Supply S.Nett Parts

1) 1set	Rear bumper clips	✓	n/c	\$	30.00 ✓
Sub total S.Nett Parts					\$ 30.00

L/charges

1)	To remove & refit right ultrasonic sensor & sensor retainer, reset reverse sensor light. Check wiring.	\$	60.00	30
2)	To remove & replace rear bumper. Align & adjust rear bumper and tail gate	\$	250.00	280 200
3)	To putty, respray painting rear bumper & ultrasonic sensor retainer in pearl white. To polish	\$	350.00	230

Sub total L/charges	\$	660.00	460
Estimated Grand total	\$	1,910.69	1710.69

L/S - 1368.55
= 1350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: