

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 28-Sep-22

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 3974 D

LKK Auto Consultants hence notify the Repairer of the following INSURANCE:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not Authorized
L1 Reg & 7750/r
Penny After Pain
4 days

Description	Qty	List Price	Amount
Bonnet	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH)	2	\$ 118.70	\$ 237.40
Bonnet Moulding	1	\$ 41.40	\$ 41.40
Bonnet Lock	1	\$ 127.30	\$ 127.30
Bonnet Insulator	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips	1	\$ 15.00	\$ 15.00
Radiator Grille	1	\$ 1,409.10	\$ 1,409.10
Flap Assy Active Air Upper, (RH)	1	\$ 824.60	\$ 824.60
Front Number Plate garnish	1	\$ 188.00	\$ 188.00
Front Bumper Cover	1	\$ 481.10	\$ 481.10
Front bumper top cover	1	\$ 476.30	\$ 476.30
Front Bumper Sponge	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (RH)	1	\$ 186.50	\$ 186.50
Front Bumper Moulding Centre Upper	1	\$ 368.50	\$ 368.50
Front Bumper Moulding	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner	1	\$ 285.10	\$ 285.10
Front bumper lower grille	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding	1	\$ 127.60	\$ 127.60
Front Bumper Lip	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (RH)	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (RH)	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (RH)	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs	1	\$ 25.00	\$ 25.00
Front Bumper Grille (RH)	1	\$ 186.90	\$ 186.90
Front bumper air duct (RH)	1	\$ 153.80	\$ 153.80
Day Light , RH	1	\$ 642.50	\$ 642.50
Headlamp Support Panel Assy	1	\$ 1,139.30	\$ 1,139.30
Headlamp(RH)	1	\$ 3,987.30	\$ 3,987.30
Horn Unit (RH)	1	\$ 72.80	\$ 72.80
Radiator Inverter	1	\$ 884.80	\$ 884.80
Radiator	1	\$ 710.50	\$ 710.50
Radiator fan blower motor assy	1	\$ 1,459.60	\$ 1,459.60
Radiator Air Guard (RH)	1	\$ 76.40	\$ 76.40
Radiator Air Guard, Upr (RH)	1	\$ 127.50	\$ 127.50
Front Fender(RH)	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel side support (RH)	1	\$ 238.80	\$ 238.80
Front Fender Apron Panel (RH)	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(RH)	1	\$ 329.00	\$ 329.00
Front Fender Shield (RH)	1	\$ 164.70	\$ 164.70
Aircon Condenser	1	\$ 663.60	\$ 663.60
Viper Container ASSY	1	\$ 385.40	\$ 385.40

211030

Front Wheel Rim (RH)	sn	1	\$ 1,124.20	\$ 1,124.20	X
Front Wheel Hub assy (RH)	sn	1	\$ 678.50	\$ 678.50	X
Front Wheel Hub Cap	sn	1	\$ 346.40	\$ 346.40	X
Front Shock Absorber(Assy)(RH)	sn	1	\$ 372.50	\$ 372.50	X
Front Shock Absorber Mounting (RH)	sn	1	\$ 372.50	\$ 372.50	X
Front Drive Shaft (RH)	sn	1	\$ 1,136.70	\$ 1,136.70	X
Front drive shaft extension RH	sn	1	\$ 1,125.80	\$ 1,125.80	X
Rack & Pinion Assy	sn	1	\$ 2,387.40	\$ 2,387.40	X
STG Tie Rod	sn	1	\$ 125.60	\$ 125.60	X
STG Tie End	sn	1	\$ 94.70	\$ 94.70	X
Stabilizer Bar	sn	1	\$ 326.80	\$ 326.80	X
Stabilizer Bar Link	sn	1	\$ 92.10	\$ 92.10	X
Front Suspension Lower Arm (RH)	sn	1	\$ 596.80	\$ 596.80	X
Knuckle Arm (RH)	sn	1	\$ 663.60	\$ 663.60	X

SUB TOTAL \$ 31,136.10

LESS 20% \$ 6,227.22

DISCOUNTED TOTAL \$ 24,908.88

Front Number Plate	sn SN	1	\$ 25.00	\$ 25.00	X
Front No Plate Trim Cover	sn SN	1	\$ 30.00	\$ 30.00	X
COOLANT	sn SN	1	\$ 45.00	\$ 45.00	X
Emblem-Blue Drive (RH)	sn SN	1	\$ 26.60	\$ 26.60	X
Front Tyre(RH)	sn SN	1	\$ 216.00	\$ 216.00	X

SUB TOTAL \$ 342.60

Labour Charge

Panel Beating		1	\$1,600.00	\$1,600.00	600l
Spray Painting Charge		1	\$1,200.00	\$1,200.00	600l
Wiring Charge		1	\$100.00	\$100.00	20l
Tuff Kote		1	\$100.00	\$100.00	60l
Towing Charge		1	\$80.00	\$80.00	50l
Four Wheel Alignment	nn	1	\$120.00	\$120.00	X
Remove/Refix Undercarriage (Frt)	nn	1	\$400.00	\$400.00	X
Remove/Refix Radiator		1	\$90.00	\$90.00	50l
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	100l
Remove/Refix Steering Rack/Wheel/Dr Shaft	nn	1	\$150.00	\$150.00	X
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150l

TOTAL LABOUR \$4,520.00

ESTIMATE TOTAL \$29,771.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com