

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC22009404/Evy3
	300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date:	23/09/2022
			Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SLE 2387C	Veh. Inspected	FBF 7439S
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VP05/026318	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	23/09/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	Description of Damages			
5.			Information	
	Accident Date	20/09/2022	Inspection Date	23/09/2022
	Survey held at	RIGHT CLICK AUTOWORKS PTE LTD		
		7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608		
5a.	. Re		emarks	
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.			
	B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.			
	C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			