

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN		Ref:	CS3/LPC22009404/Evy3e2		
	300 BEACH ROAD SINGAPORE 1995		Date:	30/09/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLE 2387C	Veh. Inspected	l	FBF 7439S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VP05/026318	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		23/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CBR150R	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	CS150R0006368	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	60/70-17	MAXXIS		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/70-17	MAXXIS		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE O/S, N/S BODY AND REAR				
5.	General Information					
	Accident Date	20/09/2022	Inspect Date /	Time	23/09/2022 (03:20 PM)	
	Survey held at	RIGHT CLICK AUTOWORKS PTE LTD				
		7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22009404/Evy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser