

4 Days.
 1 month repair
 After repair photos 26/9/22



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51 & 53
 SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)
 TEL : +65 6745 6706 FAX : +65 64843653
 EMAIL : contact@revoperformance.com.sg
 WEBSITE : www.revoperformance.com.sg
 GST REG NO : 201200256H

M/S : MS First Capital Insurance Ltd
 36 Robinson Road #16-01
 City House Singapore 068877
 TEL : 65073848
 ATTN : Motor Claim Department
 Your Ref No : SLZ 8811 U
 Claim Type : Third Party
 Accident Date : 14/09/2022
 TP Veh Reg No : SBS 6535 K

Date : 26 September 2022
 Policy No : 5126665508
 Veh Reg No : SLZ 8811 U
 Make / : JEEP / WRANGLER
 Model : UNLIMITED SAHARA 3.6 AT
 Chassis No : 1C4BJWLG3CL189778
 Engine No : GCL189778
 Reg Date : 04/05/2012

ESTIMATE REPAIR COST TO VEHICLE NO : SLZ 8811 U

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
	Special Net				
1	Rear tailgate / <i>bu</i>	\$ 1,852.50	1	\$ 1,852.50	
2	Rear tailgate door lock / <i>cut</i>	\$ 190.00	1	\$ 190.00	
3	Sticker door latch & stabilizer swing gate X	\$ 196.00	1	\$ 196.00	
4	Rear tailgate hinges top & lower X	\$ 270.00	2	\$ 540.00	
5	Rear tailgate hinges covers top & lower X	\$ 180.00	2	\$ 360.00	
6	Rear tailgate strap retaining X	\$ 293.00	1	\$ 293.00	
7	Rear tailgate door handle X	\$ 208.30	1	\$ 208.30	
8	Rear tailgate exhauster / <i>re</i>	\$ 140.00	1	\$ 140.00	
9	Rear tailgate trim panel / <i>re</i>	\$ 120.00	1	\$ 120.00	
10	Rear bumper / <i>re</i>	\$ 2,936.40	1	\$ 2,936.40	
11	Rear number plate lamp	\$ 90.60	2	\$ 181.20	
12	Rear number plate	\$ 50.00	1	\$ 50.00	
13	Rear number plate support / <i>re</i>	\$ 170.00	1	\$ 170.00	
14	Rear reverse camera	\$ 280.00	1	\$ 280.00	
15	Rear canopy cover / <i>new & old</i>	\$ 846.00	1	\$ 846.00	nn
	<i>cut tailgate plate</i>				
				\$ 8,363.40	\$ 8,363.40
	Labour				
16	Panel beating	\$ 900.00	1	\$ 900.00	<i>400</i>
17	Check wiring	\$ 120.00	1	\$ 120.00	<i>200</i>
18	To remove and replace reverse camera	\$ 80.00	1	\$ 80.00	<i>40</i>
19	To spray painting	\$ 620.00	1	\$ 620.00	<i>200</i>
				\$ 1,720.00	\$ 1,720.00

XNN



REVO PERFORMANCE PTE LTD

BLK 1 KAKI BUKIT AVE 6 #02-51 & 53
SINGAPORE 417883 (AUTOBAY@KAKI BUKIT)
TEL : +65 6745 6706 FAX : +65 64843653
EMAIL : contact@revoperformance.com.sg
WEBSITE : www.revoperformance.com.sg
GST REG NO : 201200256H

M/S : MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House Singapore 068877
TEL : 65073848
ATTN : Motor Claim Department
Your Ref No : SLZ 8811 U
Claim Type : Third Party
Accident Date : 14/09/2022
TP Veh Reg No : SBS 6535 K

Date : 26 September 2022
Policy No : 5126665508
Veh Reg No : SLZ 8811 U
Make / : JEEP / WRANGLER
Model : UNLIMITED SAHARA 3.6 AT
Chassis No : 1C4BJWLG3CL189778
Engine No : GCL189778
Reg Date : 04/05/2012

ESTIMATE REPAIR COST TO VEHICLE NO : SLZ 8811 U

NO	DESCRIPTION	U/PRICE	QUANTITY	LIST PRICE	AMOUNT
	TOTAL				\$ 10,083.40

TOTAL : SINGAPORE DOLLARS TEN THOUSAND EIGHTY THREE AND CENTS FORTY ONLY.

AUTHORISED SIGNATURE