



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22009407/Any3e2 Date: 20/12/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 619M	Veh. Inspected	SLB 6912B	
Policy No.	D-21098472MVPC	Coverage (\$)	0.00	
Claim No.	D22002983MVPC	Excess (\$)	0.00	
Assign From	AINI BINTE	Assign Date	23/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT FLUENCE	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1LZLF0E54828290	Colour	BRONZE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	TOURADOR	6 mm	
L/H Front Tyre	215/50 R17	TOURADOR	6 mm	
R/H Rear Tyre	215/50 R17	TOURADOR	6 mm	
L/H Rear Tyre	215/50 R17	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2022	Inspection Date	26/09/2022	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	