

Vehicle Damage Assessment Report for [GBL7016Y]

Estimate Created: 22/11/2022 07:33 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 22/11/2022 07:51 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	Ergo Insurance	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Hiace
Engine Type			
License Plate Number	GBL7016Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at \$6307.27 with 5 days for repair

Insurlogic 1 (22/11/2022 07:51)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BONNET		1	300.00	10.00 %	330.00
FRONT BONNET HINGE LH		1	50.00	10.00 %	55.00
FRONT BONNET LOGO		1	55.00	10.00 %	60.50
FRONT BONNET INNER LOCK		1	110.00	10.00 %	121.00
FRONT CORNER PANEL		1	85.00	10.00 %	93.50
FRONT BUMPER		1	250.00	10.00 %	275.00
FRONT BUMPER LOWER GRILLE		1	185.70	10.00 %	204.27
FRONT BUMPER SIDE RETAINER		1	75.00	10.00 %	82.50
FRONT BUMPER REINFORCEMENT		1	185.00	10.00 %	203.50
FRONT BUMPER TOP BEAM		1	145.00	10.00 %	159.50
HEADLAMPS L/R		1	760.00	10.00 %	836.00
AIRCON CONDENSER		1	550.00	10.00 %	605.00
FRONT GRILLE BASE		1	380.00	10.00 %	418.00
FRONT GRILLE INNER		1	380.00	10.00 %	418.00
FRONT TOP SUPPORT PANEL		1	180.00	10.00 %	198.00
FRONT WASHER TANK		1	95.00	10.00 %	104.50
RADIATOR		1	550.00	10.00 %	605.00
BRACE PANEL		1	50.00	10.00 %	55.00
FRONT BUMPER CLIPS		1	30.00	10.00 %	33.00

Parts Subtotal 4,857.27

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT NUMBER PLATE		1.0	30.00	0.00 %	30.00

Materials Subtotal 30.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
-------------	------	------	---------------	-------

REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	600.00	0.00 %	600.00
CHECK WIRING	RnR	20.00	0.00 %	20.00
RNR AIRCON CONDENSER AND TOP UP GAS	RnR	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	700.00	0.00 %	700.00
General Labor Subtotal				720.00
Paint Labor Subtotal				700.00
Labor Subtotal				1,420.00

Summary

Repair Cost	6,307.27
Discount(0 %)	(0.00)
	6,307.27
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	6,307.27