

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melody Teoh

Date: 27 Sep 2022

## **Preliminary Advice**

Vehicle No	: GBL7016Y	Accident Date	: 21/09/2022
Make	: TOYOTA HIACE	Policy No.	: DMCG22002171
Assignment Date	: 23/09/2022	Excess	: S\$500.00
Date of Inspection	: 26/09/2022	Est. Duration of Repair	: 5
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 12,821.17
Revised Amount	:S\$ 3,719.73
Check Items (Estimated)	:S\$ 3,974.98
Total	:S\$ 7,694.71

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 65,000.00
COE / PARF Rebate	:S\$ 21,241.00
Salvage Value	:S\$

Margin for Repair

:S\$ 43,759.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.