



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22009414/Gvy3
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)			Date:	23/09/2022
POLICE LOGISTICS BASE (PLB)				
1 HEMMANT ROAD SINGAPORE 438675			Code:	SPF
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SKA 1219U	
	Policy No.	Coverage (\$)	0.00	
	Claim No. T/20220921/7043	Excess (\$)	0.00	
	Assign From HAFIZUL FARHAN	Assign Date	23/09/2022	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 21/09/2022	Inspection Date	23/09/2022	
	Survey held at MW BROTHERS AUTO REPAIRS 319 BRADDELL ROAD SINGAPORE 579707			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				