



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22009415/Ecy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	20/10/2022
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKA 1219U	Veh. Inspected	GBB 9984S
Policy No.		Coverage (\$)	0.00
Claim No.	T/20220921/7043	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	23/09/2022
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JN1SC2F24Z0801590	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/80 R15	DUNLOP	4 mm
L/H Front Tyre	175/80 R15	DUNLOP	4 mm
R/H Rear Tyre	175/80 R15	DUNLOP	4 mm
L/H Rear Tyre	175/80 R15	DUNLOP	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/09/2022	Inspection Date	23/09/2022
Survey held at	Blk 467 Bukit Batok West Ave 8 MSCP S 651467		
Repairer	-		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	