



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/11/2022
User ID LauSW
Section A - Accident Details

Registration Number	SHC4926S
Case Reference Number	TAX/09/22/2056
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN TECK AUN
Type of Accident	Head to Rear
Accident Date and Time	22/9/2022 5:40 PM
Accident Reported Date and Time	23/9/2022 9:16 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116347
Special Instruction to ARC, if any	TOWED \$40 / REAR RIGHT
Prepared Date and Time	23/9/2022 9:49 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$300.00
Total Spray Cost	\$1,494.00	\$400.00
Total Spare Part Cost	\$6,562.67	\$1,313.84
Total Other Cost	\$556.00	(\$363.84)
TOTAL COST	\$9,626.67	\$1,650.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	23/09/2022 4:30 PM	23/09/2022 4:08 PM
Signature		
Remarks	Lumpsum repair / resurvey after repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2210-0103	Invoice Number	
Quotation Date	11.10.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,014.00	\$300.00
Total Labour	\$1,014.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$403.84)
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$556.00	(\$363.84)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Not Given
		52462470 30	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace
		52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Not Given
		52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Check
		52576470 40	RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given
		52592470 40	SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given

✓
X
✓
✓
✓
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/11/2022

User ID LauSW

		5216116010	CLIPS PIECE, FRT & RR BUMPER	1.00	\$4.80	25.00	\$3.60	Replace	Replace	✓
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$623.50	0.00	\$0.00	Replace	Not Given	X
		5256547900	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
		5256647900	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
		5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
		9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace	Replace	✓
		8155147281	LENS & BODY, REAR COMBINATION LAMP , RH	1.00	\$489.00	10.00	\$440.10	Replace	Replace	✓
		8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
		8158147010	LENS & BODY ASSY , RR BUMPER , RH	1.00	\$544.40	10.00	\$489.96	Replace	Replace	✓
		8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
		8149747020	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
		8149847020	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
		6556547010	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$37.70	0.00	\$0.00	Replace	Not Given	X
		6563747060	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given	X
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
Total					\$8,248.30		\$1,313.84			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	1,313.84	
+	300.00	
+	440.00	
	2,053.84	L/S \$1,650/-
	-20%	
	1,643.07	